

^ - 6.1

c-71

5791

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUARTERS, DELHI FIRE SERVICE, CONNAUGHT PLACE

Dated: 13/05/2022

No. F6/DFS/MS/WZ/EH/2022/327

To,

The Joint Commissioner of Police,
Licensing Unit, 1st floor, Police Station,
Defence Colony, New Delhi.
addelep.lic-dl@nic.in

Sub: - Inspection report in r/o Bikanervala Foods Private Limited Located at Shop No. 28, GF, FF, SF, Adarsh Bhawan Co-op. Society, West Punjabi Bagh, New Delhi: - 10026.

Sir,


This is in reference to the online application received through MHA portal vide ID-Online ID 2022040505611 dated 05/04/2022, regarding issuance of Fire Safety Certificate in respect of aforesaid restaurant. In this connection, it is to inform you that the premises was inspected by officers concerned of this department on 04/05/2022 in the presence Sh. Lalit (Manager) to check the fire safety arrangements provided in the building.

During the course of inspection, it was observed that the said eating house/restaurant is running at Ground, 1st & 2nd floor in a building comprised of Basement + Ground + 03 Upper Floor. FSC was issued by this department vide letter no. F6/DFS/MS/WZ/2019/1198 dated 06/06/2019. The fire safety arrangements such as Fire Extinguishers, First-Aid Reels, Automatic Fire Detection and Alarming System, MOEFA, Public Address System, Terrace Pump, Overhead Water Tank & Exit Signage are provided. However, following shortcoming was observed: -

1. One Staircase is provided in basement against requirement of 02 staircases.
2. Smoke Management System Found Removed in Basement.
3. First Aid- Hose Reels provided but not functional.
4. Automatic Fire Detection and Alarming System provided but not functional.
5. MOEFA provided but not functional.
6. P.A System is provided but not functional.
7. Terrace fire pump of capacity 900lpm provided but not functional.
8. Overhead water storage tank capacity 2000ltr provided against requirement of 5000ltr.
9. Exit Signage's are found removed.
10. Fire Check Door (FCD) is found removed in Basement.

In view of above Shortcomings the application for Issuance of Fire safety Certificate is rejected. The occupancy of the Building/ premises in absence of requisite fire safety arrangements shall be at the risk and liabilities of the Owner/occupier. The licensing issuing authority/statutory authority is requested that premises should not be allowed to run till it provide all necessary fire arrangements.

Yours faithfully


(Dharampal Bhardwaj)
Dy. Chief Fire Officer
West Zone

Copy to: -

1. The Owner/ Occupier M/s. Bikanervala Foods Private Limited Located at Shop No. 28, GF,FF,SF, Adarsh Bhawan Co-op. Society, West Punjabi Bagh, New Delhi - 110026.
2. The DHO, West Zone, SDMC, Shivaji Enclave, Raja Garden, New Delhi-110027. Email Id :
- (dhowest_zone@gmail.com)