

C-19

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI-110001

No: F.6/DFS/MS/School/WZ/2022/ 220

Dated: 13/05/2022

To

The Principal,
Kapila Public School,
02, Sandesh Vihar, Pitampura,
Delhi- 110034.

Sub.-: Regarding issuance of Fire Safety Certificate in r/o Kapila Public School, 02, Sandesh Vihar, Pitampura, Delhi- 110034.

Sir,

Please refer to your letter No. KPS/MCD/FIRE/06/22 dated 27.03.2022 on the subject cited above. In this connection, it is to inform you that the aforesaid school building have been inspected by the officer concerned of this department on 04.05.2022 to check the status of the shortcomings already pointed out by this department vide letter dated 11.06.2020, 16.05.2018 and 04.06.2010.

During the course of inspection, it was observed that the school building is comprised of ground plus two upper floors served by single staircase having width 0.81 mt. fire safety arrangements such as fire extinguishers, hose reel, terrace pump, overhead water tank capacity 2000 lts etc. found provided. However, following shortcomings were observed: -

1. One additional staircase having width atleast 0.75 mt. is required.
2. Terrace pump is provided but not functional.
3. Hose reel hose is provided but not functional.
4. Capacity of overhead water tank is less than required capacity of 2500 lts.

In view of the above, 'Fire Safety Certificate' cannot be granted at this stage. You are requested to rectify the shortcomings under intimation to this department.

Yours faithfully

(Dharampal Bhardwaj)
Dy. Chief Fire Officer
West Zone

Copy to: -

1. The Director of Education, Govt. of NCT of Delhi, Old Secretariat, Delhi.

-for information please.