

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI  
HEADQUARTERS: DELHI FIRE SERVICE: CANNAUGHT PLACE  
NEW DELHI- 110 001

No.F6/DFS/MS/School/2022/NDZI 223

Dated: 13/05/2022

To,

The Manager  
S. R. Public School,  
A-140, Part No. 3, School Line, Soniya Vihar,  
Delhi-110094.

**Subject:** -Regarding issuance of Fire Safety Certificate in r/o S. R. Public School located at A-140, Part No. 3, School Line, Soniya Vihar, Delhi-110094.

Sir,

With reference to your letter No. S.R.P.4 dated 18/04/2022 received in this department diary No 646 on dated 21/04/2022 on the subject cited above. In this regard, it is to inform you that, the inspection of the above said premises was carried out by the officer concerned of this department in presence of Mr. Attar Singh, Manager of the school on dated 02/05/2022. During the inspection it was observed that the shortcomings as communicated earlier vide letter No. F6/DFS/MS/School/2020/198 dated 18/03/2020 have not been complied as yet (The copy of the same is enclosed for reference).

In view of the above Fire Safety Certificate cannot be considered at this stage. You are once again requested to rectify the said shortcoming under intimation to this office for further consideration in the matter.

Yours faithfully

  
11/5/22

(Dr. S. K. Tomar)  
Dy. Chief Fire Officer

o/c  
R.

Copy to:-

The Director of Education, EDMC  
Plot No. 18-24, Udyog Sadan, Patparganj Industrial Area, Delhi-110092

**GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI  
HEADQUARTERS: DELHI FIRE SERVICE: CANNAUGHT PLACE  
NEW DELHI- 110 001**

No.F6/DFS/MS/School/2020/ 198

Dated 18/03/2020

To,

The Principal,  
S.R. Public School,  
A-140, Part No. 3, School Line,  
Soniya Vihar, Delhi-110094.

**Sub:- For Renewal of Fire Safety Certificate.**

Sir,

With reference to your letter no. S.R.P-12 dated 23/12/2019 on the subject cited above, it is informed that officer concerned of this department inspected the school from fire safety point of view in presence of Ms. Beena Sharma, Principal of the School on dated 05/02/2020. The School building comprises of ground plus two upper floors. During the course of inspection following observations were made:-

1. An overhead water tank having 10,000 liters capacity is required to be provided exclusively for firefighting systems.
2. A fire pump with 450 liters per minute discharge at 40 meters head (4kgf/sq.cm.) is required to be provided at terrace level.
3. Hose reels containing 30m of length and 20mm bore terminating in to a shut-off nozzle of 5mm outlet connected to the pump shall be provided for every 1000sqm. of covered area subject to a minimum of one hose reel per floor of the school building, are required to be provided.
4. Exit Signs are required to be provided in the school building at all exits.

In view of the above, the school building cannot be considered for issuance of Fire Safety Certificate at this stage. Therefore, you are requested to provide the above mentioned fire safety arrangements under intimation to this office for further course of action.

Yours Faithfully,

(Sunil Chawdhary)  
Dy. Chief Fire Officer

Copy to:-

The Director of Education, EDMC  
Udyog Sadan, Plot No. 419, FIE,  
Patparganj, Delhi -92