GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUATERS: DELHI FIRE SERVICE: NEW DELHI-110001

No: F.6/DFS/MS/School/WZ/2022/ 238

Dated: 20/05/2022

To

Sh. Sanjeev Goel, Rational Educational Society (Regd.), NS-15, FD-Block, Pitampura, New Delhi- 110034.

Sub.:- Regarding issuance of Fire Safety Certificate in r/o Rational Educational Society (Regd.), NS-15, FD-Block, Pitampura, Delhi- 110034.

Sir,

Please refer to your E-mail dated 01.04.2022 on the subject cited above. In this connection, it is to inform you that the aforesaid school building have been inspected by the officer concerned of this department on 10.05.2022 to check the provision of fire safety arrangements provided in the school building.

During the course of inspection, it was observed that the said school building is comprised of ground plus three upper floors served by two nos. of staircase having width 1.50 mts & 0.90 mt. Fire safety arrangements such as fire extinguishers, hose reel, terrace pump, overhead water tank capacity 10,000 lts etc. found provided. However, following shortcomings were observed: -

- 1. Width of main gate is less than required width of 4.5 mts.
- 2. Width of alternate staircase is less than required width of 1.50 mts.
- 3. Exit signages are not provided.

In view of the above, 'Fire Safety Certificate' cannot be granted at this stage. You are requested to rectify the shortcomings under intimation to this department.

Yours faithfully

Director

Delhi Fire Service

Copy to: -

1. The Director of Education, Govt. of NCT of Delhi, Old Secretariat, Delhi.

-for information please.