

**GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEAD QUARTERS: DELHI FIRE SERVICE: NEW DELHI-110001**

No. F.6/DFS/MS/WZ/misc/1231

Dated: 31/05/2022

To

Sh. Ritik Jindal,
Dynamic Fitness & Crossfit Gymnasium,
Basement, AM-62, Maharishi Dayanand Marg,
Shalimar Bagh, New Delhi- 110088.

Sub: - Regarding renewal of fire safety certificate in r/o Dynamic Fitness & Crossfit Gymnasium located at Basement, AM-62, Maharishi Dayanand Marg, Shalimar Bagh, New Delhi-110088.


Sir,

This is in reference to E-mail dated 09.05.2022 on the subject cited above. In this regard, it is submitted that the premises was inspected by the officer concerned of this department on 20.05.2022 in presence of Sh. Rohit (manager) to check the status of the fire safety arrangements provided in the premises.

During inspection, it was observed that the said gym is running in basement floor in a building comprised of basement, stilt, ground plus three upper floors. Fire safety arrangements such as fire extinguishers, overhead water tank capacity 6000 lts, detection system, sprinkler system, MOEFA etc. found provided. However, following shortcomings were observed: -

1. Terrace pump capacity 900 lpm is provided but not functional.
2. Hose reel hose in basement floor is provided but not functional.
3. Sprinkler system in basement floor is provided but not functional.
4. Down comer system is provided but not functional.
5. Overhead tank capacity 6000 lts is provided against requirement of 20,000 lts.
6. Smoke management system is not provided.
7. Exit signages found removed.

In view of above shortcomings, the application for renewal of fire safety certificate is not considered at this stage & rejected. The occupancy of the building/premises in absence of requisite fire safety measures shall be at the risk and liabilities of the owner/occupier.


(Dharampal Bhardwaj)
Dy. Chief Fire Officer
West Zone