

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEAD QUARTERS: DELHI FIRE SERVICE NEW DELHI-110001

No. F6/DFS/MS/School/2022/NDZI/265

Dated 27/05/2022

To,

The Principal,
EDMC Nigam Pratibha Vidyalaya,
F-Block, Dilshad Colony,
Delhi 110095

Sub:- Regarding Issuance of Fire Safety Certificate in r/o EDMC Nigam Pratibha Vidyalaya,
F-Block, Dilshad Colony, Delhi 110095.

Sir,

This is in reference to your letter No. EDMC/EE(E)-I/SHN/2021-22/D-40 dated-02/05/2022 on the subject cited above. In this regard, it is to inform you that, the inspection of the above said premises was carried out by the officer concerned of this department on 19/05/2022 in presence of Mrs. Sita, Principal . During inspection it was observed that the shortcomings as communicated earlier vide letter No. F6/DFS/MS/School/2019/145 dated 10/01/2019 are yet to be rectified. Copy of the same is enclosed for your ready reference.

Yours faithfully



(Dr. S.K. Tomar)
Dy.Chief Fire Officer



Copy to:-

- 1) The Director of Education, EDMC,
Udyog Sadan, Plot No.419, FIE,
Patparganj Industrial Area,
Delhi-110092.
- 2) The Ex. Eng. (Elect.)-II,
Shahdara (North)Zone,
EDMC, Office of Executive Engineer (Elect)-II,
MCD Zonal Office Buildings, Keshav Chowk,
G.T. Road, Near Shyam Lal College.

C/22

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUARTERS: DELHI FIRE SERVICE: CANNAUGHT PLACE
NEW DELHI- 110 001

No. F6/DFS/MS/School/2018/145

Dated: 10/11/19

To,

The Principal,
EDMC Nigam Pratibha Vidyalaya,
F-Block, Dilshad Garden,
Delhi 110095

Sub:- Regarding Issuance of Fire Safety Certificate in r/o EDMC Nigam Pratibha Vidyalaya,
F-Block, Dilshad Garden, Delhi 110095.

Sir,

This is in reference to your letter No. D/56/DC II/EDMC/SHN dated 20/08/2018 on the subject cited above. In this connection, it is to inform you that the officer concerned of this department has carried out the inspection of the above mentioned school from fire safety point of view in presence of Mrs. Poonam Roy, Principal of the School to verify the compliance of shortcomings already communicated by this department vide letter No. F6/DFS/MS/School/2015/2264 dated 06/10/15 and was observed that following shortcomings have not been complied.

1. A fire pump having 220 LPM provided in place of 450 LPM output at 40 meters head as required.
2. Exit Signage not provided.

In view of above, the building can not be considered for issue of Fire Safety Certificate at this stage. Therefore you are suggested to rectify the above mentioned shortcomings under the intimation to this department for further course of action.

Yours faithfully


(Vipin Kental)
Chief Fire Officer

o/c

by

Copy to:-

The Director of Education, EDMC
Udyog Sadan, Plot No. 419, FIE,
Patparganj, Delhi 92