



**GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEAD QUARTERS: DELHI FIRE SERVICE NEW DELHI-110001**

No. F6/DFS/MS/School/2022/NDZ/ 277

Dated: 05/06/2022

To,

The Principal,
EDMC Nigam Prathibha Vidyalaya,
Nand Nagri, C-II, Shahdara
Delhi-110093.

Subject: -Regarding issuance of Fire Safety Certificate in r/o EDMC Nigam Prathibha Vidyalaya, Nand Nagri C-II, Shahdara, Delhi-110093.

Sir,

Please refer to letter. EDMC/EE(E)-I/SHN/2021-22/D-40 dated-02/05/2022 on the subject cited above. In this regard, it is to inform you that, the inspection of the above said premises was carried out by the officer concerned of this department in presence of Mrs. Mohan Singh, on dated 25/05/2022. During the inspection it was observed that the shortcomings as communicated earlier vide letter No. F6/DFS/MS/School/2019/NDZ/6823 dated 15/11/19 are yet to be rectified. Copy of the same is enclosed for your ready reference.

In view of the above Fire safety Certificate cannot be considered at this stage, you are once again requested to rectify the said shortcoming under intimation to this office for further consideration in the matter.

Yours faithfully

(Dr. S.K Tomar)
Dy.Chief Fire Officer

Copy to:-

- 1) The Director of Education,
Udyog Sadan, Plot No.419, FIE,
Patparganj Industrial Area, Delhi-110092
- 2) The Ex. Eng. (Elect.)-II,
Shahdara (North)Zone,
EDMC, Office of Executive Engineer (Elect)-II,
MCD Zonal Office Buildings, Keshav Chowk,
G.T. Road, Near Shyam Lal College.

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEAD QUARTERS: DELHI FIRE SERVICE NEW DELHI-110001

No.F6/DFS/MS/School/2019/ 6823

Dated: 15/11/19

To,
The Principal,
M/S EDMC Pratibha Vidyalaya
Nand Nagri C-II, Shahdara,
Delhi-110093

Subject: -Regarding grant of Fire Safety Certificate in r/o M/S EDMC Pratibha School
Nand Nagri C-II, Shahdara, Delhi-110093.

Sir,

With reference to your letter No. nil dated 07/09/2019 on the subject cited above, it is informed that officer concerned of this department carried out inspection of the school from fire safety point of view in presence of Principal of the school. During the course of inspection, it was observed that the building comprised of ground plus three upper floors and are provided with fire extinguishers and first aid hose reels which were functional at the time of inspection. Discharge capacity and head of the Fire Pump was not ascertained in absence of technician/documents, so you are requested to supply following information at the earliest:

1. Discharge capacity and Head of the fire pump mounted at terrace for feeding hose reels.

Yours faithfully



(Sunil Chawdhary)
Dy. Chief Fire Officer



Copy to:-

The Director of Education, EDMC
Udyog Sadan, Plot No. 419, FIE,
Patparganj, Delhi 92