GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEAD QUARTERS: DELHI FIRE SERVICE: NEW DELHI – 110001

No. F6/DFS/MS/School/WZ/2022

Dated: 03/06/2022

To.

The Principal, Saraswati Bal Mandir School, A-2, Paschim Vihar, New Delhi-110063.

Sub. :- Renewal of Fire Safety Certificate in r/o Saraswati Bal Mandir School Located at A-2, Paschim vihar, New Delhi-110063.

Sir,

Please refer to your email dated 13.04.2022 on the subject cited above. In this connection, it is to inform you that the said School building has been inspected by the officer concerned of this department on 24.05.2022 in the presence of Sh. Pawan Paliwal (Office Incharge) to see compliance of the shortcomings communicated vide this department letter no. F6/DFS/MS/School/WZ/2022/130 dated 23.03.2022.

During the course of inspection, it has been observed that the Management has rectified some of the shortcomings the status is under:-

S. no.	Shortcomings	Status
1.	First Aid Hose Reels Hose found removed at ground floor	Rectified
2.	Fire Pumps are provided but found nonfunctional	Not yet Rectified

In view of the above shortcoming, the application for issuance of Fire Safety Certificate is rejected. The occupancy of the building/premises in absence of requisite fire safety arrangements shall be at the risk and liability of the owner/occupier. The Education Authority may take suitable necessary action as deemed fit.

Yours faithfully,

(Dharampal Bharc

Dy. Chief Fire Office

(West Zone

Copy to:-

1. The Director, Directorate of Education Old Secretariat Delhi – 110054.