

296

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUARTERS : DELHI FIRE SERVICE, NEW DELHI - 110001

No. F6/DFS/MS/GH/NDZ/2022/ 406

Dated: 30/05/2022

To

The Joint Commissioner of Police (Licensing),
1st Floor, Police Station Defence Colony,
New Delhi.

Sub: Regarding renewal of Fire Safety Certificate in respect of **M/s Vakil Guest House**, located at **735-739, Motor Market, Jama Masjid, Delhi-06.**


Sir,

With reference to online application I.D. no. 2022043008990 dated 30.04.2022 on the subject cited above, it is informed that the guest house was inspected by Assistant Divisional Officer (SPM) from this department on 19.05.2022 in the presence of Mr. Sarzil (Owner's son) and it was observed that building is comprised of Ground + 04 upper floors. During inspection, following shortcomings were observed:

1. First Aid Hose reel found non functional.
2. CO detectors not provided required as per gazette notification dated 27.05.2019.
3. Fire extinguishers found non functional.
4. Fire pump found not in auto start mode.
5. Exit signage not provided.
6. Occupancy at fourth floor is not allowed as per gazette notification dated 27.05.2019.
7. Plans of all the floors have not been uploaded on the portal.

In view of above shortcomings, the application for issuance for Fire Safety Certificate is rejected. The occupancy of the building/premises in absence of requisite fire safety arrangements shall be at the risk and liability of the owner/occupier. The Authority/Statutory Authority may take suitable necessary action as deemed fit.

Yours faithfully,


27/5/22

(Dr. S.K. Tomar)

Dy. Chief Fire Officer

Tel: 011-23412025

8
27/5

Copy to:-

M/s Vakil Guest House, located at 735-739, Motor Market, Jama Masjid, Delhi-06.