

**GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI  
HEADQUARTERS: DELHI FIRE SERVICE: CANNAUGHT PLACE  
NEW DELHI- 110 001**

No. F6/DFS/MS/School/2022/NDZI/ 294

Dated 07/06/2022

To,

The Principal,  
EDMC Primary School,  
F-2, Sunder Nagri,  
Delhi-110093.

Sub:- Regarding Issuance Fire Safety Certificate in R/o EDMC Primary School at F-2, Sunder Nagri, Delhi-93.

Sir,

With reference to your letter No. **EDMC/EE(E)-I/SHN/2021-22/D-40 dated-02/05/2022** on the subject cited above. In this connection, it is to inform you that the officer concerned of this department has carried out the inspection of the above mentioned school from fire safety point of view on dated 25/05/22 in presence of Mrs. M.J Kerketa (Principal). The following points / shortcomings were noticed in the building which is comprised of ground plus two upper floors .

1. Access /approach road width is less than 6 meters.
2. Width of staircases 1.50 mtr. wide not provided.

In view of above, the building can not be considered for issuance of Fire Safety Certificate at this stage. Therefore you are suggested to rectify the above mentioned shortcomings under the intimation to this department for further course of action.

Yours faithfully,

(Atul Garg)  
Director

Copy to:-

1. The Director of Education, MCD  
Udyog Sadan, Plot No. 419, FIE,  
Patparganj, Delhi 92
2. The Ex. Eng. (Elect,)-II,  
Shahdara (North)Zone,  
MCD, Office of Executive Engineer (Elect)-II,  
MCD Zonal Office Buildings, Keshav Chowk,  
G.T. Road, Near Shyam Lal College.