

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUARTERS, DELHI FIRE SERVICE, CONNAUGHT PLACE
NEW DELHI

No. F6/DFS/MS/WZ/2022/ 1333

Dated: 09/ 06 /2022

To,

The Sunil K Jain (Vice President),
Aggarwal Plaza H 7,
Netaji Subhash Place,
Pitampura, New Delhi.

Sub:- Inspection report in r/o Aggarwal Plaza H 7, Netaji Subhash Place, Pitampura, New Delhi.

Sir,


Please refer to your Letter dated:- 08/04/2022 on the subject cited above. In this connection, it is to inform you that the premises was inspected by officer concerned of this department on 24/05/2022 in the presence of Sh. Ajay Chauchan to see the functioning of fire safety equipments provided in the Building.

During inspection, It has been observed that the said building comprised of Basement + Ground + 3 upper floors was issued FSC vide letter No. F6/DFS/MS/2019/WZ/1037 dated 15/05/2019. Fire safety arrangements such as Smoke Management System, Fire Extinguishers, MOEFA, First Aid hose reels, Over Head water storage tank, Underground water tank capacity, Pumping Arrangements are provided. However the following shortcomings were observed: -

1. Automatic fire detection and alarming system provided but not functional
2. Main Pump 2850LPM, Stand by Pump 2850LPM & Jockey Pump 2x225LPM Provided but not on auto mode.
3. Exit sinages found removed.

In view of above, application for renewal of Fire safety Certificate is rejected. The occupancy of the Building/ premises in absence of requisites fire safety Arrangements Shall be at the risk and liabilities of the Owner/occupier. The licensing issuing authority/statutory authority is requested that premises should not be allowed to run till it provide all necessary fire arrangements.

Yours faithfully


(Dharampal Bhardwaj)
Dy. Chief Fire Officer
West Zone

Copy To:-

1. The Dy. Director (Bld.), Delhi Development Authority, Vikas Sadan, INA, Delhi