

**GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUARTERS: DELHI FIRE SERVICE: CANNAUGHT PLACE
NEW DELHI- 110 001**

No. F.6/DFS/MS/School/2022/NDZ/349

Dated 23/06/2022

To,

The Ex. Engineer (Elect.)-II
Shahdara (North Zone)
EDMC Office of the Executive Engineer (Elect.)-II
MCD Zonal Office Building, Keshav Chowk,
G.T. Road, Near Shyam Lal Collage,
Delhi-110053

Subject: - Regarding Issuance of Fire Safety Certificate in r/o EDMC Primary School at L-Block, Sunder Nagri, Delhi-110093.

Sir,

With reference to your letter No. EDMC/EE(E)-I/SHN/2021-2022/D-40 dated 02/05/2022 on the subject cited above. In this connection this is to inform you that, the inspection of the above said premises was carried out by the officer concerned of this department on dated 01/06/2022. During the inspection it was observed that the shortcomings as communicated earlier vide letter No. F.6/DFS/MS/School/2019/NDZ/7045 dated 26/11/2019 have not been complied as yet (The copy of the same is enclosed for reference).

In view of the above Fire Safety Certificate cannot be considered at this stage. You are once again requested to rectify the said shortcoming under intimation to this office for further consideration in the matter.

Yours faithfully


21/6/22

(Dr. S. K. Tomar)
Dy. Chief Fire Officer

Copy to:-

1. The Director of Education, MCD
Dr. S.P. Mukherjee Civic Center, JLN Marg,
New Delhi-110002
2. The Principal
EDMC Primary School at L-Block, Sunder Nagri, Delhi-110093.

o/c ↓

C-8

**GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI- 110001**

No. F6/DFS/MS/School/2019/NDZ/ 7045

Dated 26/11/19

To.

The Principal,
EDMC Primary School,
L-Block, Sunder Nagri,
Delhi-110093

Sub:- Regarding Fire Safety Certificate.


Sir,

With reference to your letter on the subject cited above, it is informed that officer concerned of this department inspected the school from fire safety point of view in presence of Ms. Savita Arora, Principal of the School on dated 19/10/2019. The School building comprises of ground plus first floor. During the course of inspection following observation was made:-

1. The school is not accessible to fire engines as road width is less than 6 meters.

In view of the above, the school building cannot be considered for issuance of Fire Safety Certificate at this stage. Therefore, you are requested to provide the above mentioned fire safety arrangements under intimation to this office for further course of action.

Yours Faithfully,



(Sunil Chawdhary)
Dy. Chief Fire Officer

o/c J.S.

Copy to:-

The Director of Education, EDMC
Udyog Sadan, Plot No. 419, FIE,
Patparganj, Delhi -92