



GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUARTERS: DELHI FIRE SERVICE: CANNAUGHT PLACE
NEW DELHI- 110 001

No. F.6/DFS/MS/School/2022/NDZ/1351

Dated - 23/06/2022

To,

The Ex. Engineer (Elect.)-II
Shahdara (North Zone)
EDMC Office of the Executive Engineer (Elect.)-II
MCD Zonal Office Building, Keshav Chowk,
G.T. Road, Near Shyam Lal Collage,
Delhi-110053

Subject: - Regarding Issuance of Fire Safety Certificate in r/o EDMC Primary School at Brahampuri Old, Gali No. 12, Delhi-110053.

Sir,

With reference to your letter No. EDMC/EE(E)-I/SHN/2021-2022/D-40 dated 02/05/2022 on the subject cited above, In this connection this is to inform you that, the inspection of the above said premises was carried out by the officer concerned of this department on dated 01/06/2022. During the inspection it was observed that the shortcomings as communicated earlier vide letter No. F.6/DFS/MS/School/2021/79 dated 17/02/2021 have not been complied as yet (The copy of the same is enclosed for reference).

In view of the above Fire Safety Certificate cannot be considered at this stage. You are once again requested to rectify the said shortcoming under intimation to this office for further consideration in the matter.

Yours faithfully

(Dr. S. K. Tomar)
Dy. Chief Fire Officer

Copy to:-

1. The Director of Education, MCD
Dr. S.P. Mukherjee Civic Center, JLN Marg,
New Delhi-110002
2. The Principal
EDMC Primary School at Brahampuri Old, Gali No. 12, Delhi-110053.

c.12
c/14

**GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI- 110001**

No.F6/DFS/MS/School/2021/ 79

Dated 17/02/2021

To,

The Principal,
EDMC Primary School,
Brahampuri old, Gali. No.12,
Delhi-53

Sub:- Request for issuing a Fire Safety Certificate.

Sir,

With reference to your e-mail ID:- hos1152127@gmail.com dated 21/01/2021 on the subject cited above, it is informed that officer concerned of this department inspected the school from fire safety point of view in presence of Mrs. Geeta Sharma, Principal of the School on dated 10/02/2021. The School building comprises of ground plus two upper floors. During the course of inspection following observations were made:-

1. The premises is not accessible to fire engines.
2. A fire pump with 450 liters per minute discharge at 40 meters head (4kgf/sq.cm.) is required be Provide at terrace level.
3. Firefighting system which has been provided in the building, was not functional at the time of Inspection.

In view of the above, the school building cannot be considered for issuance of Fire Safety Certificate at this stage.

Yours Faithfully,


12/2/21

(Dr. S. K. Tomar)
Dy. Chief Fire Officer

Copy to:-

The Director of Education, EDMC
Udyog Sadan, Plot No. 419, FIE,
Patparganj Industrial Area, Delhi-92