



GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEAD QUARTERS: DELHI FIRE SERVICE: CONNAUGHT PLACE NEW DELHI-110001

No. F6/DFS/MS/School/2022/NDZ/ 346

Dated 23/06/2022

To.

The Principal. Lovely Public Middle School, 5. Old Geeta Colony, Delhi-110031

Subject:- Regarding renewal of Fire Safety Certificate in r/o Lovely Public Middle School located at 5, Old Geeta Colony, Delhi-110031.

Sir,

With reference to your letter No. LPMS/GC/2022-232 dated 13/05/2022 on the subject cited above. In this connection, this is to inform you that the inspection of the above said premises was carried out by the officer concerned of this department on dated 08/06/2022 in presence of Sh. Vipin Sharma. During the inspection it was observed that the shortcomings as communicated earlier vide letter No. F.6/DFS/MS/School/2022/NDZ/65 dated 11/02/2022 have not been complied as yet (The copy of the same is enclosed for reference).

In view of the above Fire Safety Certificate cannot be considered at this stage. You are once again requested to rectify the said shortcoming under intimation to this office for further consideration in the matter.

Yours faithfully

(Dr. S. K. Tomar) Dy. Chief Fire Officer

Copy to:-

The Joint Director of Education (Land & Estate), Directorate of Education, Lucknow Road, Delhi-110054

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI- 110001

No. F.6/DFS/MS/School/2022/NDZ/ 75

Dated: 11/02/2022

129

To,

The Principal, Lovely Public Middle School, 5, Old Geeta Colony, Delhi-110031

Subject:- Renewal of Fire Safety Certificate.

Sir,

With reference to email ID lpsjupiter@yahoo.co.in dated 12/11/2021 on the subject cited above, it is informed that officer concerned of this department inspected the school from fire safety point of view in presence of Ms. Sunita Dhingra (A.M.) on dated 14/01/2022. The school building comprises of ground plus three upper floors. During the course of inspection following observations were made:-

- 1. An overhead water tank having 2,000 liters capacity is provided against the required capacity of 10,000 liters.
- 2. Firefighting systems (fire pump & hose reel) which have been provided in the building, was not functional.

In view of the above, the school building cannot be considered for issuance of Fire Safety Certificate at this stage. Therefore, you are requested to provide the above mentioned fire safety arrangements under intimation to this office for further course of action.

Yours faithfully,

Etomy 912122

(Dr. S. K. Tomar) Dy. Chief Fire Officer

Copy to:-

The Joint Director of Education (Land & Estate), Directorate of Education, Lucknow Road, Delhi-110054