



**GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI  
HEADQUARTERS: DELHI FIRE SERVICE: CANNAUGHT PLACE  
NEW DELHI- 110 001**

No. F.6/DFS/MS/School/2022/NDZ/355

Dated 24/06/2022

To,

The Ex. Engineer (Elect.)-II  
Shahdara (North Zone)  
EDMC Office of the Executive Engineer (Elect.)-II  
MCD Zonal Office Building, Keshav Chowk,  
G.T. Road, Near Shyam Lal Collage,  
Delhi-110053

**Subject:** - Regarding Issuance of Fire Safety Certificate in r/o Nigam Pratibha School at Usmapur, Shahdara North, Delhi-110053.

Sir,

With reference to your letter No. EDMC/EE(E)-I/SHN/2021-2022/D-40 dated 02/05/2022 on the subject cited above. In this connection this is to inform you that, the inspection of the above said premises was carried out by the officer concerned of this department on dated 01/06/2022. During the inspection it was observed that the shortcomings as communicated earlier vide letter No. F.6/DFS/MS/School/2021/NDZ/200 dated 09/04/2021 have not been complied as yet (The copy of the same is enclosed for reference).

In view of the above Fire Safety Certificate cannot be considered at this stage. You are once again requested to rectify the said shortcoming under intimation to this office for further consideration in the matter.

Yours faithfully

(Dr. S. K. Tomar)

o/c  
R.  
Dy. Chief Fire Officer

Copy to:-

1. The Director of Education, MCD  
Dr. S.P. Mukherjee Civic Center, JLN Marg,  
New Delhi-110002
2. The Principal  
Nigam Pratibha School at Usmapur, Shahdara North, Delhi-110053.

**GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI  
HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI- 110001**

No. F.6/DFS/MS/School/2021/NDZ/ 200

Dated: 9/04/2021

To,

The Principal,  
Nigam Pratibha School,  
Usmanpur, II<sup>nd</sup> Shift,  
Shahdara North, EDMC,  
Delhi-110053

**Subject:-Regarding issuance of Fire Safety Certificate .**

Sir,

With reference to your online letter dated 26/02/2021 on the subject cited above, it is informed that officer concerned of this department inspected the school from fire safety point of view in presence of Mr. Dharampal Singh, Principal of school on dated 10/03/2021. The school building comprises of ground plus two upper floors. During the course of inspection following observations were made:-


1. A fire pump with 450 liters per minute discharge at 40 meters head (4kgf/sq.cm.) is required to be provided at terrace level.
2. Hose Reels which has been provided in the building was not functional at the time of inspection.

In view of the above, the school building cannot be considered for issuance of Fire Safety Certificate at this stage. Therefore, you are requested to provide the above mentioned fire safety arrangements under intimation to this office for further course of action.

Yours Faithfully,



(Dr. S. K. Tomar)  
Dy. Chief Fire Officer



Copy to:-

The Director of Education,  
East Delhi Municipal Corporation,  
419, Udyog Sadan, Patparganj Industrial Area,  
Delhi-1100