GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELIH FIRE SERVICE: NEW DELHI-110001

No. F.6/DFS/MS/School/2022/SZ/340

Dated: 23/06/2022

To

The Principal, R.L Public School, L- Block, Street No - 15, Mahipalpur Extension, New Delhi 110037

Sub: Regarding issuance of Fire Safety Certificate (FSC) in r/o R. J Public School, L- Block, Street No -15, Mahipalpur, Extension, New Delhi 110037.

Sir.

This has reference to with Gmail of dated 11/06/2022 on the subject cited above. In this connection, it is to inform you that the above mentioned premise was visited by the officer concerned of this department on 16/06/2022 and observed that the shortcoming intimated vide letter of even no 183 dated 05/04/2021 has not been complied yet. (Copy Enclosed for ready reference).

In view of above Shortcomings, the application for issuance Fire Safety Certificate is The occupancy of the building/premises in absence of requisite fire safety arrangements shall be at the risk and liability of the owner/occupier. The Licensing authority/ Statutory Authority may take suitable necessary action as deemed fit. The action taken report in this concerned may also be forwarded to this department.

Yours faithfully,

(SUNIL CHAWDHARY) DY. CHIEF FIRE OFFICER (SZ) **DELHI FIRE SERVICE**

Copy to:-

1. Directorate of Education, Govt. of NCT of Delhi, Old Secretariat, New Delhi 110054.

GOVERNMENT OF NATIONAL CAPITAL TERRITOTY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI- 110001

No. F.6/DFS/MS/School/2021/SZ/ \ \ \ \ \ \ \ 3

Dated: ..\$.../2021

To

The Principal, R. J Public School, L- Block, Street No – 15, Mahipalpur Extension, New Delhi 110037

Sub.:- Renewal of Fire Safety Certificate in r/o R. J Public School, L- Block, Street No - 15, Mahipalpur Extension, New Delhi 110037

Sir,

This has reference to your Gmail dated 08/03/2021 on the subject cited above. In this connection, the said school premises have been inspected by concerned nominated of this department on 18/03/2021 in the presence of Sh. R. K Sagwan (Manager). During the inspection it was observed that school is comprised of Basement, Ground plus three upper floors. (Basement Closed & 3rd Floor used as residence by the owner). The shortcomings observed are as below.

- 1. First Aid Hose Reels are not working.
- 2. Terrace level pump capacity 450 LPM provided not working.
- 3. Exit signage found removed.

In view of above shortcomings, renewal of Fire Safety Certificate cannot be considered at this stage. You are requested to rectify the shortcoming under intimation to this department for further action in the matter.

Yours faithfully,

(Sunil Chawdhary) Dy. Chief Fire Officer (SZ) Delhi Fire Service

Copy to: -

1. Directorate of Education, Govt. of NCT of Delhi, Old Secretariat, New Delhi-1 10054