

**GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUARTERS: DELHI FIRE SERVICE: CANNAUGHT PLACE
NEW DELHI- 110 001**

No. F.6/DFS/MS/School/2022/NDZ/366

Dated-30/06/2022

To,

The Principal
EDMC Pratibha Vidyalaya
Shastri Part Extn. Delhi-110053.

Subject: - Regarding Issuance of Fire Safety Certificate in r/o EDMC Pratibha Vidyalaya at Shastri Part Extn. Delhi-110053.

Sir,

With reference to your letter No. nil dated 22/04/2022 on the subject cited above. In this connection this is to inform you that, the inspection of the above said premises was carried out by the officer concerned of this department on dated 06/06/2022 in presence of Mrs. Rekha Rani, Principal. During the inspection it was observed that the shortcomings as communicated earlier vide letter No. F.6/DFS/MS/School/2021/NDZ/647 dated 13/12/2021 have not been complied as yet (The copy of the same is enclosed for reference).

In view of the above Fire Safety Certificate cannot be considered at this stage. You are once again requested to rectify the said shortcoming under intimation to this office for further consideration in the matter.

Yours faithfully



(Dr. S. K. Tomar)

o/c Dy. Chief Fire Officer
e.

Copy to:-

1. The Director of Education, MCD
15th Floor, E- Block, Dr. S.P. Mukherjee Civic Center, JLN Marg,
New Delhi-110002

C-15

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI- 110001

No. F.6/DFS/MS/School/2021/NDZ/647

Dated: 13/12/2021

To,

The Principal,
EDMC Primary School,
Buland Masjid, Shastri Park Extension
Delhi-110053

Subject:- Request for site visit.

Sir,

With reference to letter No. E.E. (Elect.)-II/Shah (S)/2021-2022/D-570 dated 27/10/2021 on the subject cited above, it is informed that officer concerned of this department inspected the school from fire safety point of view in presence of Sh. Manoj Kumar Aggarwal, Principal of the school & Sh. Kuldeep Kumar Singh, J.E. (Elect.) Shahdara South Zone on dated 29/11/2021. The school building comprises of ground plus two upper floors. During the course of inspection following observations was made:-

1. One staircase of width 1.50 meter or an additional staircase of 0.75 meter width is not provided.

In view of the above, the school building cannot be considered for issuance of Fire Safety Certificate at this stage. Therefore, you are requested to provide the above mentioned fire safety arrangements under intimation to this office for further course of action.

Yours faithfully,

(Ajay Garg)
Director

13/12/2021
NL

Copy to:-

1. The Director of Education, EDMC
Udyog Sadan, Plot No. 419, FIE,
Patparganj Industrial Area, Delhi-110092
2. The Ex. Engr. (Elect.)-II/SSZ
EDMC, Office of Executive Engineer (Elect.)-II/SSZ,
2nd Floor Technical Laboratory,
Near NH-24 Gazipur, Delhi-110096