



**GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUARTERS: DELHI FIRE SERVICE, CONNAUGHT PLACE
NEW DELHI-110001**

No. F6/DFS/MS/School/WZ/ 2022/401

Dated 13/07/2022

To,

The Principal,
N.C. Jindal Public School,
Road No.-73, Punjabi Bagh,
New Delhi – 110026.

Sub: - Inspection report in respect of N.C. Jindal Public School Located at Road No. 73, Punjabi Bagh, New Delhi-110026.

Sir,

With reference to your Email dated 15/06/2022 on the subject cited above. In this connection, it is to inform you that the said premises was inspected by the officer concerned of this department on 24/06/2022 in the presence of Sh. R.K. Sharma (Maintenance) to see the functioning of the fire safety equipments provided in the building.

During inspection, it has been observed that the School is running in total two blocks, 1st block is (Sr. Sec. Block) comprised of G + 02 upper floors & 2nd block is (Primary section) comprised of G + 02 upper floors, all are inter connected, was issued FSC vide letter No.F6/DFS/MS/SCHOOL/2019/1431 dated 12/07/2019. Fire safety arrangements such as, Fire Extinguishers, First-Aid Hose reels, Terrace pump, etc. are provided in the building.

However, following shortcomings were observed: -

1. First Aid Hose reels are provided but not functional.
2. Terrace fire pump of 900 lpm & Jockey pump 180 lpm is provided but not on automode.
3. Exit signage's found removed at some palaces.

In view of above shortcomings, the application for Renewal Fire Safety Certificate is rejected. The occupancy of the building/premises in absence of requisite fire safety arrangements shall be at the risk and liability of the owner/occupier. The statutory authority may take suitable necessary action as deemed fit.

Yours faithfully

(Dharampal Bhardwaj)
Dy. Chief Fire Officer
Delhi Fire Service

Copy to:-

1. The Directorate of Education Old Secretariat Delhi – 110054.

o/c SFP
07/07/2022