

**GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI**  
**HEADQUARTERS, DELHI FIRE SERVICE, NEW DELHI-110001**

No. F6/DFS/MS/School/WZ/2022/ 385

Dated: 8/7 /2022

To,

The Principal,  
Govt. Sarvodaya Bal Vidyalaya,  
Moti Nagar,  
New Delhi – 110015.

Sub: **Regarding Issuance of NOC fire safety point of view in r/o Govt. Sarvodaya Bal Vidyalaya Located at Moti Nagar, New Delhi – 110015.(School ID-1516010 Old Building).**

Sir,

Please refer to your Email dated 30/05/2022 on the subject cited above. In this connection, it is to inform you that the said building/premises was re-inspected by the officer concerned of this department on 27/06/2022 in the presence of Mr. Anand Dalal (Estate Manager) and observed that the shortcomings already communicated by this department vide letter no. F6/DFS/MS/School/2012/1121 dated 23/05/2014, F6/DFS/MS/School/2015/319 dated 12/02/2015, F6/DFS/MS/School/2018/1944 dated 10/05/2018 & F6/DFS/MS/ /WZ/2019/School/5645 dated 18/09/2021, is still not complied. (Copy Enclosed)

In view of above Shortcomings the application for issuance of Fire safety Certificate is rejected. The occupancy of the Building/ premises in absence of requisites fire safety arrangements shall be at the risk and liabilities of the Owner/occupier. The statutory authority is requested that premises should not be allowed to run till it provide all necessary fire arrangements.

Yours Faithfully

  
(Atul Garg)  
Director  
Delhi Fire service

Copy to:

1. Director of Education, Old Secretariat, Civil Lines, Delhi-110054.

o/c 8/7  
05/07/2022

GOVERNMENT OF NATIONAL CAPITAL TERRITORY  
HEADQUARTERS, DELHI FIRE SERVICE, CONNAUGHT PLACE  
NEW DELHI

Dated: 23/05/14

No. F6/DFS/MS/School/2014/1121

To,

The Principal,

Government Sarvodaya Bal Vidyalaya,

Moti Nagar,

New Delhi – 110015.

Subject: Regarding issuance of NOC from fire safety point of view in respect of Government Sarvodaya Bal Vidyalaya, Moti Nagar, New Delhi – 110015.

Sir,

Please refer to your letter no. SBV/MN/Fire Safety/12/13 dated 21-12-13 on the subject captioned above. In this connection it is to inform you that the premises was visited by officer of this department on 31-03-14 to see the compliance of shortcomings communicated vide this office letter no. F6/DFS/MS/2011/School/ 2818 dated 01-11-2011.


The following shortcomings were observed:

1. Width of the staircase is 135 cms against the required width of 150 cms. The width of staircase shall be increased to 150 cm or an additional staircase of not less than 75 cms shall be provided.
2. Hose reel not provided in the gymnasium.
3. Fire pump of 450 lpm with 40 m head not provided.
4. Overhead water storage tank of 10000 litres for fire fighting not provided.
5. Class room door width is 93 cms against required 100 cms.
6. Down comer system for gymnasium not provided.
7. Exit signages not provided.
8. Two doors of 1.5 m shall be provided in the hall.

You are requested to send compliance report of the same under intimation to this department.

In view of the above FSC from fire safety point of view can not be considered at this stage.

Yours faithfully,

  
(Vipin Kanta)  
Dy. Chief Fire Officer,  
Delhi Fire Service,  
Ph: 011-23846352

0/6 @ 19/5