



GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI- 110001



933

No.F6/DFS/MS/School/NDZ/2022/438

Dated: 28/7/2022

To

Mr. Amar Chand Meena,
Assistant Engineer (Electrical),
PWD, Govt. of Delhi, Sub-Division-4,
Education Electrical Edn. 1 Division (N),
Zakhira, Rama Road, Delhi -15.

Sub:- Regarding issuance of Fire Safety Certificate in respect of **Govt. Girls Sr. Sec. School, Chasma Building, Ballimaran, Delhi (School I.D. no. 2127025).**

Sir,

This has reference to email dated 06.06.2022 on the subject cited above. In this connection, it is to inform you that the above mentioned school building was visited by the officer concerned of this department on dated 07.07.2022 and observed that the school building is comprised of ground + 03 upper floors. Further, the width of road to access the school building is 2 meters against the required width of 6 meters and already communicated by the department vide letter no. F6/DFS/MS/School/NDZ/2021/526 dated 29.09.2021(copy enclosed for ready reference).

In view of above, the issuance of Fire Safety Certificate (FSC) for the aforesaid school is rejected. The occupancy of the building/ premises in absence of requisite Fire Safety Certificate shall be at the risk & liability of school authority.

Yours faithfully,

(Atul Garg)

Director

Delhi Fire Service

Tel: 01123414000

olc

8c
25/7

Copy to:-

1. The Director of Education, Govt. of Delhi, Old Secretariat, Delhi.
2. The Principal, Govt. Sr. Sec. School, Chasma Building, Ballimaran, Delhi.

e/31 e/28

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUARTERS: DELHI FIRE SERVICE, NEW DELHI - 110001

No. F6/DFS/MS/School/NDZ/2021/526

Dated: 29/09/2021

To

Mr. Amar Chand Meena,
Assistant Engineer (Electrical),
PWD, Govt. of Delhi, Sub-Division-4,
Education Electrical Edn.1 Division (N),
Zakhira, Rama Road, Delhi-15.

**Sub: Regarding issuance of Fire Safety Certificate in respect of Govt. Girls Sr. Sec. School,
Chasma Building, Ballimaran Delhi (School I.D no. 2127025).**

Sir,

With reference to your email letter dated 18.09.2021 on the subject cited above, it is informed that the school was visited by Assistant Divisional Officer (SPM) from this department on 21.09.2021 and it was found that work was still in progress in the newly constructed Ground + 3 upper floor school building. No responsible person from the building side was available on site hence inspection of the building could not be carried out. Further the school building is not accessible to the fire engines and abuts on 2 meters road only.

In view of above, the issuance of Fire Safety Certificate (FSC) for the aforesaid school cannot be considered at this stage. It is also requested to share the phone number of the official from building side to coordinate the inspection.

Yours faithfully,



((Dr. S.K. Tomar)

Dy. Chief Fire Officer

Tel: 011-23412025

c/c 
28/9

Copy to:-

1. The Director of Education, Govt. of NCT of Delhi, Old Secretariat, Delhi.
2. The Principal,
Govt. Girls Sr. Sec. School, Chasma Building, Ballimaran Delhi (School I.D no. 2127025).