## GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE, NEW DELHI-110001

No. F6/DFS/MS/WZ/2022/School/ 435

To,

The Principal, P.P International School, LD Block, Pitampura, New Delhi- 110034.

Sub: Regarding renewal of fire safety certificate in r/o P.P International School, LD- Block, Pitampura, New Delhi- 110034.

Sir,

Please refer to your letter/Form 'J' dated nil received vide outdoor diary No. 2570 dated 20.06.2022 on the subject cited above. In this regard, it is to inform you that the school building was inspected by the officer concerned of this department in your presence to check the status of the fire safety arrangements provided in the school building.

During inspection it has been observed that the said building is comprised of basement, ground plus four upper floors. Basement floor is served by 06 staircases & 01 ramp. Ground & upper floor are served by 06 staircases. Fire safety arrangements such as overhead water storage tank capacity 50,000 lts, terrace pumps capacity 900 & 220 LPM, hose reels, down comer, automatic sprinkler system in basement etc. found provided. However, following shortcomings were observed: -

- 1. Fire/smoke check doors found removed at some places.
- 2. Exit signages found removed.

In view of the above shortcomings, fire safety certificate cannot be renewed at this stage. You are requested to rectify the above mentioned shortcomings and submit point wise compliance for further necessary action in this matter.

Yours faithfully,

(Dharampal Bhardwaj)
Dy. Chief Fire Officer

West Zone

Copy to: -

1. The Directorate of Education, Old Secretariat, Delhi- 110054.