

C-24

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUARTERS : DELHI FIRE SERVICE, NEW DELHI – 110001

No. F.6/DFS/MS/School/NDZ/2022/ 464

Dated: 7 / 8 /2022

To

The Principal,
Francis Girls Senior Sec. School,
17, Darya Ganj, Delhi-110002.

Sub: Regarding renewal of Fire Safety Certificate (FSC) in r/o Francis Girls Senior Sec. School located at 17, Darya Ganj, Delhi-02.

Sir,

This is in reference to letter no. nil dated 25.05.2022 on the subject cited above. In this connection, it is to inform you that the above mentioned premise was visited by the officer concerned of this department on dated 25.07.2022 and observed that the shortcomings intimated vide letter no. F.6/DFS/MS/2011/1794 dated 29.07.2011 & F6/DFS/MS/School/2013/2145 dated 04.09.2013 have not been complied yet. (Copy enclosed for ready reference).

In view of above shortcomings, the application for issuance Fire Safety Certificate is rejected. The occupancy of the building/premises in absence of requisite fire safety arrangements shall be at the risk and liability of the owner/occupier.

You are requested to provide fire safety arrangements as per the Circular of Director of Education, Govt. of NCT of Delhi vide their letter no. F16/Estate/CC/Fire Safety/2011/3298-3398 dated 01.03.2011.

Yours faithfully,

Encl:- As above.

S.K. Dua
03/08/22

(S. K. Dua)
Dy. Chief Fire Officer
Delhi Fire Service

o/c
S.K. Dua
03/08

Copy to:-

The Director of Education,
Govt. of NCT of Delhi, Old Secretariat, Delhi.

C-16

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI-110001
Fax: 23412593, E-mail: cfohq.dlfire@nic.in, Tel:- 011-23414333

No. F6/DFS/MS/School/2013/2195

Dated: 04/09/13

To,

The Principal,
Francis Girls Sr. Sec. School,
17-Darya Ganj,
Delhi – 110 002.

Sub: Opening of Emergency Gate in the back boundary wall as per norms of Fire Safety


Sir,

Please refer to your letter no. Nil dated 18-07-2013 on the subject cited above. In this regard it is to inform you that the above said premises was inspected by the officer concerned of this department in presence of the Mrs Sarita Miller, Principal on 21/08/2013 to verify the fire safety arrangements as per Delhi Fire Service Act-2010

The school building is comprised of ground plus one upper floor served with one staircase from ground to first floor having width 95 Cms. The other available staircase was found not in use as the management has partitioned the building at first floor rendering only one staircase available for use. The school Management has not rectified the shortcomings communicated vide this office letter no. F.6/DFS/MS/2011/1794 dated 29-07-2011.

You are requested to provide fire safety arrangements as per the Circular of Director of Education, Govt of NCT of Delhi vide their letter no.F.16/Estate/CC/Fire Safety/2011/3298-3398 dated 01-03-2011.

Yours faithfully,


(Dr. G. C. Misra)
Chief Fire Officer
Delhi Fire Service

% 