



C.7

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS, DELHI FIRE SERVICE, CONNAUGHT PLACE

NEW DELHI

No. F6/DFS/MS/SZ/2022/School 478

Dated: 12 /0.5/2022

To,

The Principal,<sose1821294@gmail.com> Dr. B.R Ambedkar School of Specialized Excellence Sector – 06, Dwarka, New Delhi - 110075.

Subject: Issuance of Fire Safety Certificate in r/o Dr. B.R Ambedkar School of Specialized Excellence Sector – 06, Dwarka, New Delhi - 110075.(School ID-1821294)

Sir,

Please refer to your Email dated-04/07/2022 on the subject mentioned above. In this connection it is to inform you that the premises was inspected by the officer concerned from this department on 11/07/2022 in the presence of Sh. Girjesh Kumar Mishra.

During the course of inspection flowing shortcomings are observed.

- 1. The class romm doors are obstructing the corridor passage..
- 2. Sliding doors are found fixed at the stairs. All the stairs must be kept clear from any obstruction & free from lock & key.
- 3. Exit signages found not provided.
- 4. The terrace pumps are found nonfunctional in auto mode.

You are requested to comply the abovementioned shortcomings under intimation to this department.

In view of the above shortcomings Fire Safety Certificate cannot be considered at this stage.

Yours faithfully,

Director Delhi Fire Service

Copy to;-

1. Directorate of Education Old Secretariat Delhi - 110054.