

## GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI- 110001



No. F6/DFS/MS/WZ/2022/School/466

Dated: 04/08 /2022

The Principal, USM Public School, Plot no. 3/47, 48, Veena Enclave, Nangloi, New Delhi-110041

## Subj.:- Regarding issuance of Fire Safety Certificate in r/o USM Public School Located at Plot no. 3/47, 48, Veena Enclave, Nangloi, New Delhi-110041.

Sir,

Please refer to your email dated 19.07.2022 on the subject cited above. In this connection it is to inform you that the said building have been inspected by the officer concerned of this department on 28.07.2022 in your presence to check compliance of shortcomings issued by this department vide letter no. F6/DFS/MS/2013/1919 dated 08.08.2013.

During inspection, it have been observed that the shortcomings issued by this department vide above said letter has not been rectified yet.

In view of the above shortcomings, Fire safety Certificate cannot be grant at this stage. You are advised to rectify the above mentioned shortcomings under intimation to this department for taking further necessary action.

Yours faithfully,

(Dharampal Bhardwaj)
Dy. Chief Fire Officer

(West Zone)

Copy to :-

 The Director, Directorate of Education, GNCT of Delhi, Old Secretariat Delhi – 110054

C-8

## GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE, CONNAUGHT PLACE NEW DELHI-110001

No. F6/ DFS/MS/2013/1979

Dated 8/8/1/3

To

The Manager, U.S.M. Public School (Recognized), Veena Enclave, Nangloi, New Delhi –110041.

Sub:- Inspection report in respect of U.S.M. Public School (Recognized), Veena Enclave, Nangloi, New Delhi –110041 from fire& safety point of view.

Sir,

With reference to your letter No. Nil dated 29/05/2013 on the subject noted above, it is informed that the said school premises was inspected by the officer concerned of this department on 10/07/2013 in the presence of Smt. Sunita (Teacher).

During inspection it has been observed that the school premises was earlier issued FSC by this department vide letter No. F6/MS/DFS/06/3277 dated 07/11/2006 for ground floor only. Now school management has added 1<sup>st</sup> floor & 2<sup>nd</sup> floor on existing ground floor. Fire Safety arrangements such as Fire Extinguishers were found provided only.

The following shortcomings were observed during the time of inspection:-

- 1. First Aid Hose Reel on each floor has not been provided.
- 2. Terrace pump of 450 LPM capacity has not been provided.
- 3. Over Head Tank of 10,000ltr. has not been provided.

4. Exit signage not provided.

5. The width of both the staircase is to be increased up to 1.50mtr.

The School premises is not meeting the requirement of Fire & Safety guidelines issued by the Directorate of Education circular dated 01.03.2011.

In view of above, Fire Safety Certificate from the Fire & Safety point of view cannot be considered at this stage.

Yours faithfully

(Santokh Singh) Chief Fire Officer Delhi Fire Service Phone:-23414250

E-mail: cfowz,dlfire@nic.in

## Copy to :-

1. The Director of Education, Gov. of NCT of Delhi, Old Secretariat, Delhi.