



**GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI  
HEADQUARTERS: DELHI FIRE SERVICE: CANNAUGHT PLACE  
NEW DELHI- 110 001**

No. F.6/DFS/MS/School/2022/NDZ/

497

Dated 23/8/22

To,

The Principal,  
EDMC Pimary School,  
Arvind Nagar, Ghonda,  
Delhi- 110053

Sub:- Regarding Issuance Fire Safety Certificate r/o EDMC Pimary School located at Arvind Nagar, Ghonda, Delhi- 110053.

Sir,

This is in reference to your letter No. EDMC/EE(E) -I/SHN/2021-22/D-40 dated 02/05/2022 on the subject cited above. In this connection, it is to inform you that the officer concerned of this department has carried out the inspection of the above mentioned School from fire safety point of view in presence of Dr. Krishan Kant, Principal of the School. The building comprised of ground plus two upper floors. Following shortcomings were observed during the time of inspection.

1. 10 nos. fire extinguishers provided in place of 14 nos. as required.
2. First-Aid hose reel provided but not functional.
3. The discharge capacity & head of the fire pump could not ascertained in absence of documents/technician.
4. Exit signs are required to be provided in the school building at all exits.

In view of the above, the building cannot be considered for issuance of Fire Safety Certificate at this stage. Therefore, you are requested to provide the above mentioned fire safety arrangements under intimation to this office for further course of action.

Yours faithfully

(ATUL GARG)  
DIRECTOR  
DELHI FIRE SERVICE

o/c.  
2.

Copy to:-

1. The Director of Education, MCD  
15<sup>th</sup> Floor, E- Block, Dr. S.P. Mukherjee Civic Center, JLN Marg,  
New Delhi-110002