



GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUARTERS: DELHI FIRE SERVICE, NEW DELHI-110001

No. F6/DFS/MS/2022/NDZ/

494

Dated: 23/8 /2022

To

The Manager,
Kala Niketan Sr. Sec. Bal Vidyalaya,
Durga Puri Extn., Delhi-110093.

Sub.:- Inspection Report in r/o Kala Niketan Sr. Sec. Bal Vidyalaya, Durga Puri Extn., Delhi.

Sir,

With reference to your letter No KBV/6(12)2007-08/FS/1011 dated 16/07/2022 on the subject noted above. In this connection, it is to inform you that the said building premises was inspected by the officer concerned of this department on 08.08.2022 in the presence of Mr. S.P. Sharma (Vice-Principal).


During the course of inspection it was observed that the building premises is comprised of Ground, 1st Floor, 2nd Floor & 3rd Floor Only.

However following shortcomings were observed during the time of inspection:-

1. Hose Reel provided but found nonfunctional.
2. Internal Hydrant provided but found nonfunctional.
3. Fire Pump of 220 Lit/min capacity provided but found nonfunctional.

In view of above shortcomings, the application for issuance Fire Safety Certificate is rejected. The occupancy of the building / premises in absence of requisite fire safety arrangements shall be at the risk and liability of the owner / occupier. Statutory authority may take action as deemed fit at their end please.

Yours faithfully,



(S.K. DUA)

DY. CHIEF FIRE OFFICER.

Copy to :-

1. Director of Education, Old Secretariat, Civil Lines, Delhi-110054.