

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE, NEW DELHI-110001

No: F.6/DFS/MS/School/2022/WZ/ 506

Dated: 24/08/2022

To,

The Principal, Navjeevan Modern School, Main Gonda Road, Swatantra Nagar, Narela, Delhi-110040.

Sub: - Regarding issuance of Fire Safety Certificate in r/o Navjeevan Modern School, Main Gonda Road, Swatantra Nagar, Narela, Delhi-110040.

This has reference to your letter no. nil received via outdoor diary no. 3437 dated 15.07.2022 on the subject cited above. In this connection, it is to inform you that the inspection of above said school building has been carried out by officer concerned of this department on 10.08.2022 to see the compliance of the requisite fire safety measures. Smt. Rinky (Principal) was present at the time of inspection.

During the course of inspection it was observed that previously Fire Safety Certificate was issued vide letter no. F6/DFS/MS/School/2019/1555 dated 31/07/2019 for a building comprised of Ground Floor only and now the school building comprised of Basement+Ground+ Two upper floors. Your request of issue of FSC is rejected as the following shortcomings were observed:-

- 1. Width of staircases of upper floors found 1.50 m &1.10 m against required width of 1.50 m each.
- 2. Width of staircases of basement found 2.25 m & 1.36 m against required width of 1.50 m each.
- 3. Fire check door not provided in basement.
- 4. Smoke management system not provided in basement.
- 5. First-Aid Hose Reel not provided.
- 6. Automatic Sprinkler System not provided in basement.
- 7. Terrace level fire pump of 900 lpm capacity not provided.
- 8. Over Head Water tank of 15,000 ltrs capacity not provided.
- 9. Exit Signage not provided.

You are advised to rectify the above-mentioned shortcomings for taking further action as necessary for issuance of Fire Safety Certificate.

Director Delhi Fire Service

Copy to:-

1. Director of Education, Govt. Of NCT of Delhi, Old Secretariat, New Delhi.