167



Dated: 01/9/2022

## GOVERNMENT OF NATIONAL CAPITAL TERRITOTY OF DELHI <u>HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI- 110001</u>

47

No. F6/DFS/MS/Edu./2022/SZ/ College

То

The Authorized Signature, Chandiwala Estate, Maa Anandmai Marg, Kalkaji, New Delhi - 110019.

Sub: - Regarding Fire Safety Certificate in r/o 'H, J & K' Block, Shri Banarsidas Chandiwala Sewa Smarak, Trust Society, Chandiwala Estate, Kalkaji, New Delhi - 110019

Sir,

This has reference with your Email dated 14/06/2022 on the subject cited above. In this connection, it is to inform you that the officers concerned of this department inspected the aforesaid building in presence of Ms. Puja Singh to check the compliance of fire safety arrangements from fire safety point of view and following shortcomings were observed:

- 1. Width of one staircase in basement & upper floors is 1.44m against required width of 1.5m.
- 2. Fire check doors not provided at some places.
- 3. Automatic sprinkler system is not provided in the basement.
- 4. Jockey Pump of 180 LPM capacity provided but not on auto mode.
- 5. Stand by Pump of 1620 LPM not provided.
- 6. Terrace Pump of capacity 900 LPM provided but not on auto mode.
- 7. Exit signage not provided.

In view of above Shortcomings, the application for issuance Fire Safety Certificate is rejected. The occupancy of the building/premises in absence of requisite fire safety arrangements shall be at the risk and liability of the owner/occupier. The Licensing authority/ Statutory Authority may take suitable necessary action as deemed fit.

Yours faithfully (ATUL GARG DIRECTOR OIL

## Copy To:-

1. The Executive Engineer (Bldg) SDMC Civic Centre, Minto Road, New Delhi 1100002