

C-15

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUARTERS: DELHI FIRE SERVICE: CANNAUGHT PLACE
NEW DELHI- 110001

No: F.6/DFS/MS/School/2022/SZ/ 533

Dated: 5/9/22

To,

The Principal,
Mothers Mount Global School,
J-Block, Vikaspuri, New Delhi-110018.

Sub: - Regarding issuance of Fire Safety Certificate in r/o. Mothers Mount Global School, J-Block, Vikaspuri, New Delhi-110018

Sir,

This has reference to your letter No. outdoor diary no. 3619 dated- 21/07/2022 on the subject cited above. In this connection this is to inform you that officer concerned of this department inspected the school on 22/08/2022 to verify the fire safety arrangements in accordance with the Rules. At the time of inspection Mrs. Vandana Chadha was present and it was observed that the school building is comprised of ground, first floor & tin shed at 2nd floor and have following shortcomings.

1. One of the staircases shall be provided 1.5 m wide.
2. Second staircase is not approachable through common corridor.
3. Tin-shed should be removed at terrace level.

In view of above, the fire safety certificate cannot be considered at this stage. You are requested to rectify the above shortcoming under the intimation to this department for further course of action.

Yours faithfully

(Atul Garg)
Director

Delhi Fire Service

Copy to:-

1. The Director of Education, Govt of NCT of Delhi, Old Secretariat, New Delhi-110054.