



GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI- 110001 Dated: 06/09/2022

No: F.6/DFS/MS/School/WZ/2022/ 540

To

The Er. Amar Chand Meena, Assistant Engineer (E), PWD Sub-Division 4, Edu. Elect. Edn. 1 Div. (N), Zakhira, Rama Road, Delhi-15.

Sub.:- Regarding renewal of Fire Safety Certificate in r/o New Block in Govt. Girls Sr. Sec. School, Shalamar Village, Delhi- 110088.

Sir.

This is in reference to your E-mail dated 11.08.2022 received vide ID aeepwdsd4@gmail.com on the subject cited above. In this connection, it is to inform you that the school building was inspected by the officer concerned of this department in the presence of Sh. Parveen Kumar, site engineer on 29.08.2022 to check the status of the fire safety arrangements already provided in the school building.

During the course of inspection, it was observed that the new block of the school building is comprised of ground plus three upper floors served by two staircases having width 1.80 mts each. Fire safety arrangements such as fire extinguishers, first aid hose reel, PA system, terrace pump capacity 450 LPM, overhead water tank capacity 10,000 lts etc. found provided. However, following shortcomings were observed: -

- Two terrace pumps having capacity 450 LPM each are provided but not functional.
- First aid hose reel is provided but not functional.
- Width of exits of the Multi Purpose hall located at ground floor are 1.13, 1.10 &1.05 mts against required 02 nos. of width 2.0 mts each.
- Exit signages found removed.

In view of the above shortcomings, fire safety certificate cannot be granted at this stage. You are advised to rectify the above mentioned shortcomings under intimation to this department.

Yours faithfully

Director

Copy to: -

- 1. The Principal, Govt. Girls Sr. Sec. School, Shalamar Village, Delhi- 110088.
- 2. The Directorate of Education, Old Secretariat, New Delhi.