

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI **HEADQUARTERS: DELHI FIRE SERVICE, NEW DELHI-110001**

No.

f6 Dfs ms EH 2022 559

Dated: 06/09/2022

To,

Authorized Signatory, Panch Mishthan, Hall no. 07, 79-A, Ground Floor, Dilshad Garden, Delhi - 110095.

Subject: Inspection report of M/s Panch Mishthan, Hall no. 07, 79-A Ground Floor, Dilshad Garden, Delhi - 110095, from Fire Safety and means of escape point of view.

Sir,

Please refer to your letter received through MHA Portal ID-2022080515871 dated 08/08/2022 on the subject noted above, in this connection, it is to inform you that the said premises was inspected by the officer concerned of this department on 24/08/2022 in the presence of Sh. Lokesh Gupta.

During the course of inspection it was observed that the building premises is comprised of Ground Floor only.

Following shortcomings ware observed during the time of inspection:-

- 1. Two doors of width 2.00 mtr & 1.00mtr is provided against required of 2 no. doors having width 1.50 mtr each.
- 2. Hose Reel not provided.
- 3. Internal Hydrant not provided.
- 4. Fire pump of 450 LPM capacity not provided.
- 5. Exit Signage not provided.
- 6. Over Head Tank of 20,000 ltr not provided.

In view of above shortcomings, the application for issuance Fire Safety Certificate is rejected. The occupancy of the building / premises in absence of requisite fire safety arrangements shall be at the risk and liability of the owner / occupier. The Licensing Authority / Statutory Authority may take suitable necessary action as deemed fit.

Yours faithfully,

Copy to:-

2/8

1. Joint Commissioner of Police (Lic), 1st Floor, PS: Defence colony, New Delhi-110049w.r.t. MHA portal ID-2022080515871 dated 08/08/2022.

2. Dy. Health Officer, Shahdara (North Zone), Keshav Chowk, Grand Trunk Rd (Near Shyam Lal College), Shahdara, New Delhi, Delhi 110032.

