

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI-110001

No: F.6/DFS/MS/School/SZ/2022/ 583

Dated: - 21/09/2022

To.

The Assistant Engineer (E),
Sub-Div- 1 Education Division M 1 (N),
PWD GNCT, Govt. of Delhi, ITI Campus, Pusa Road, New Delhi- 110012.

Sub.: - Regarding issuance of Fire Safety Certificate in r/o Sarvodaya Kanya Vidyalaya, Shadi Khampur, New Delhi – 110008.

Sir,

Please refer to your letter No. 54(SPS School)/PWD Edu.Sub-Divn M1-1(N)/2021-22/Camp01 dated 10.08.2022, on the subject cited above. In this connection, it is to inform you that the aforesaid school building have been inspected by the officer concerned of this department in presence of Sh. Suresh Chand Gupta (Fire Supervisor) on 02.09.2022 to check the functionability of the existing fire safety arrangements in the school building.

During inspection, it has been observed that the said school building is comprised of ground plus three upper floors (newly constructed). Fire safety arrangements such as hose reel, terrace pump, overhead water tank, fire extinguishers, exit signage etc. found provided in the school building. However, the following shortcomings were observed:-

1. One staircase width of 1.78 mts is provided against the requirement of two staircase having width of 1.50 mts each.

In view of the above shortcomings, 'Fire Safety Certificate' cannot be issued at this stage. You are requested to rectify the above-mentioned shortcomings under intimation to this department.

Yours faithfully



(Anil Garg)

Director

Delhi Fire Service

o/e 

Copy to: -

1. The Director of Education, Govt. of NCT of Delhi, Old Secretariat, Delhi
2. The Principal, Sarvodaya Kanya Vidyalaya, Shadi Khampur, New Delhi- 110008.

for information please