

C-19

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUARTERS: DELHI FIRE SERVICE, CONNAUGHT PLACE
NEW DELHI- 110001

No. F6/DFS/MS/school/2022/SZ/ 622

Dated: 30/09/2022

To,

The Manager,
A.E.S N.T. Rama Rao Memorial Sr. Sec. School,
B-3B Block, Janak Puri, New Delhi-110058

Sub: - Regarding grant of NOC from fire safety point of view in r/o A.E.S N.T. Rama Rao Memorial Sr. Sec. School, B-3B Block, Janak Puri, New Delhi-110058.

Sir,

This has reference to your letter No. Nil dated 07/09/2022 on the subject captioned above. In this connection, it is to inform you that the above mentioned school building was inspected by the officers concerned of this department on 14/09/2022 in the presence of Mrs. E. Anitha (Principal) to verify the compliance of shortcoming already communicated by this department vide letter no.F6/DFS/MS/School/2018/SZ/2504 dated 13/06/2018 and observed that shortcomings are still not rectified. The management will be held responsible for any untoward incident for the period if compliance is not made.

Yours faithfully



(Sunil Chawdhary)

Dy.Chief Fire Officer



Copy to:-

The Director of Education,
Govt. Of NCT of Delhi, Old Secretariat,
New Delhi-110054.

C 16

**GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUARTERS: DELHI FIRE SERVICE, NEW DELHI-110001**

No: F.6/DFS/MS/School/2018/SZ /2504

Dated: 13/06/18

To,

The Principal,
A.E.S N.T. Rama Rao Memorial Sr. Sec. School,
B-3 B Block, JanakPuri, New Delhi-110058.

Sub: - Regarding issuance/renewal of Fire Safety Certificate in r/o A.E.S N.T. Rama Rao Memorial Sr. Sec. School, B-3B Block, JanakPuri, New Delhi-110058.

Sir,

This has reference to your Letter No. Form 'J' dated 05.04.2018 on the subject cited above. In this connection, it is to inform you that the inspection of above said school building has been carried out by officer concerned of this department on 08.05.2018 to see the compliance of the requisite fire safety measures. Sh. D.V.S Shastri (Manager) was present at the time of inspection.

During the course of inspection it was observed that school building comprised of ground floor plus two upper floors having total ten rooms on GF, ten rooms on FF, ten rooms on SF was issued NOC by this department vide letter no. F.6/DFS/MS/2008/1029 dated 10.04.08. Now new rooms have been constructed on each floor level and having total 42 rooms (14 rooms on each floor). The upper floors are served by four staircases having width 130 cms each. The existing fire protection arrangement such as fire extinguishers, fire pumps, exit signs etc. are provided in the building. The school building is approachable to the fire fighting vehicles. The electrical wiring was seen concealed and the electric supply was passing through MCB's. The following shortcomings were observed:-

1. Door size of newly added class rooms on each floor level is 90 cms against required 120 cms.
2. Additional First aid hose reels are required on each floor.
3. Overhead water storage tank of 5000 ltrs. capacity is provided against required 10,000 ltrs capacity.

You are advised to rectify the above-mentioned shortcomings for taking further action as necessary for grant of Fire Safety Certificate.

Yours Faithfully,

U
12/6

(VIPIN KENTAL)
CHIEF FIRE OFFICER

Copy to:-

1. Director of Education,
Govt. of NCT of Delhi, Old Secretariat,
New Delhi - 110054
2. Andhara Education Society,
Dr. B.V. Nath & T.R. Rao, Memorial Sr. Sec. School,
Prasad Nagar (Karol Bagh), New Delhi-110005

Dr. B.V. Nath
05/06/18