6

## GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE, NEW DELHI- 110001

No.F6/DFS/MS/School/NDZ/2022 660

Dated: 26/10/22

То

The Principal, Queen Mary`s School, Tis Hazari, Delhi- 110054.

Sub:- Regarding issuance of Fire Safety Certificate in r/o Queen Mary's School located at Tis Hazari, Delhi – 110054.

Sir,

This has reference to letter no. QMS/GC/Aug/2022/05 dated 10.08.2022 received in this department, on the subject cited above. In this connection, this is to inform you that the school building was inspected by officer concerned from this department on 03.10.2022 in the presence of Sh. Ashok Kumar (Supervisor). During the inspection, following shortcomings were observed:-

- 1. Hose reel found non functional at some places.
- 2. Fire pump not in auto start mode.
- 3. Classes conducted in basement of science block, which is not allowed as per NBC part IV & UBBL 2016.
- 4. Domestic LPG cylinders used in school canteen.
- 5. 2000 ltrs. over head water capacity tank provided at some blocks against the required capacity of 2,500 ltrs.

In view of above shortcomings, the application for issuance for Fire Safety Certificate is rejected. The occupancy of the building/premises in absence of requisite fire safety arrangements shall be at the risk and liability of the school management. The Authority/Statutory Authority may take suitable necessary action as deemed fit.

Yours faithfully,

(S. K. Dua) Dy. Chief Fire Officer Delhi Fire Service

<u>Copy to:-</u> The Director of Education, Govt. of NCT of Delhi, Old Secretariat, Delhi.