

## GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELIII HEADQUARTERS: DELIII FIRE SERVICE: NEW DELIII- 110001



No.F6/DFS/MS/School/SZ/2022/ 665

Dated:

To

The Principal, Singhal Public School. L-1<sup>st</sup>, 2073, Near Asthal Mandir, Sangam Vihar, New Delhi-80.

Regarding renewal of Fire Safety Certificate in respect of Singhal Public School located Sub:at L-1st, 2073, Near Asthal Mandir, Sangam Vihar, New Delhi-80.

Sir,

This has reference to your letter no. 11 dated 08.09.2022 on the subject cited above, it is informed that the school building was inspected by Assistant Divisional Officer (M. Road) from this department on 14.10.2022 in the presence of Mrs. Amrita (Incharge) and it was observed that the building is comprised of comprised of 2 blocks: Ground + 3 upper floor & Ground + 2 upper floors (interconnection at all floor level). During the inspection following shortcomings was observed:-

- 1. The school building having ground + 3 upper floors block to be used as a godown of electronic items should be removed.
- 2. Hose reel found non functional.
- 3. Overhead fire tank capacity of 2,000 liters provided against the requirement of 10,000 liters.
- 4. Fire pump found non functional.
- 5. Exit sinages found removed.

In view of above shortcomings, the application for issuance for Fire Safety Certificate is rejected. The occupancy of the building/premises in absence of requisite fire safety arrangements shall be at the risk and liability of the school management. The Authority/Statutory Authority may take suitable necessary action as deemed fit.

Yours faithfully,

(Sunil Chawdhary) Dy. Chief Fire Officer

Delhi Fire Service

of the

## Copy to:-.

The Dy. Director of Education, GNCT of New Delhi DISST. South Block-C, Defence Colony, New Delhi-24.