

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI-110001

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI-110001

NO. F-6/DFS/MS/EH/SZ/2022/ 640

Dated:- 31/10/2022

To,

The Owner/Occupier,
M/s. Delia My Bar Headquarters (A unit of KBPS Hospitality LLP),
Plot No. 11, Pusa Road, Karol Bagh, New Delhi- 110005.

Sub: - Regarding issuance of fire safety certificate in r/o M/s. Delia My Bar Headquarters (A unit of KBPS Hospitality LLP), Plot No. 11, Pusa Road, Karol Bagh, New Delhi- 110005.

Sir,

Please refer to online application ID 2022090617170 dated 30.09.2022 on the subject cited above. Above said eating house running at third floor of a building comprised of basement, ground plus three upper floors. In this connection it is to inform you that the above said assembly building (Restaurant & Bar) was inspected by the officers concerned of this department from safety point of view on 18.10.2022 in presence of Sh. Ajit Singh Ajmani, Director of the restaurant.

During the course of inspection it has been observed that fire safety arrangements such as D.G set found provided. However the following shortcomings have been observed:-

- 1 Three exits door width of 1.80, 1.38 & 1.50 mts found provided against requirement of two exit doors with width of 2.0 & 1.50 mts.
- 2 Fire Check Doors are not provided in kitchen.
- 3 Smoke ventilation not provided.
- 4 Fire extinguisher found not provided.
- 5 First Aid hose reel found provided but not functional.
- 6 Smoke Detector found provided but not functional.
- 7 MOEFA found provided but not functional.
- 8 Internal hydrant system found provided but not functional.
- 9 Main electrical fire pump capacity of 2280 LPM, Diesel pump of 2280 LPM capacity along with jockey pump of 180 LPM found provided but not functional.
- 10 Exit signage & Lift signage are not provided at the places mentioned during the inspection.
- 11 Plan of underground water storage tank is not submitted by restaurant management as underground tank of 1,00,000 lts capacity with Draw off & Fire inlet connection is to be provided.

Keeping in view of above, fire safety certificate cannot be considered at this stage. You are requested to rectify the above said shortcomings for taking further necessary action in this matter.

Yours faithfully

(Ajit Singh)
Director

Ph: 011-23414000

Copy to:-

1. The Executive Engineer (Building), MCD, Karol Bagh Zone, Anand Parbat, New Delhi.