

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUARTERS: DELHI FIRE SERVICE, NEW DELHI-110001

No. F.6.DFS/MS/School/ND//2022 **689**

Dated: **14 / 11 /2022**

To

The Principal,
Govt. Girls Senior Secondary School,
Bela Road, Darya Ganj, Delhi.

Sub: Regarding issuance of Fire Safety Certificate (FSC) in **r/o Govt. Girls Senior Secondary School, Bela Road, Darya Ganj, Delhi.**

Sir,

This is in reference to letter no. GGSSS/BR/DG/2022-23/217 dated 18.10.2022 on the subject cited above. In this connection, it is to inform you that the above mentioned premise was visited by the officer concerned of this department on dated 02.11.2022 and observed that the shortcomings intimated vide letter no.F6/DFS/MS/School/2014/80 dated 13/01/2014 (copy enclosed) have not been complied yet.

In view of above shortcomings, the application for issuance Fire Safety Certificate is rejected. The occupancy of the building/premises in absence of requisite fire safety arrangements shall be at the risk and liability of the owner/occupier. The Licensing authority/ Statutory Authority may take suitable necessary action as deemed fit.

Yours faithfully,

Encl: As above.



(S. K. Dua)
Dy. Chief Fire Officer
Delhi Fire Service

o/e
82
10/11

Copy to:-

The Director of Education,
Govt. of NCT of Delhi, Old Secretariat, Delhi.

C-12

**GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUARTERS: DELHI FIRE SERVICE: CANNAUGHT PLACE
NEW DELHI- 110001**

Ph - 23412025 Email - dcfondz.dfire@nic.in

No. F6/DFS/MS/School/2014/80

Dated: 13/01/14

To,

The Principal

Govt. Girls Sec. School,

Bela Rd. Dariya Ganj, New Delhi-02.

Sub: - Regarding issue of "Fire Safety Certificate" from fire safety point of view in r/o Govt. Girls Sec. School, Bela Rd. Dariya Ganj, New Delhi-02.

Madam,

Please refer to your letter No. GGSSS/BR/DG/2013-14/303 dated 28.11.13 on the subject cited above, this is to inform you that aforesaid school building have been inspected by the officer concerned of this department in presence of Smt. Meena Gautam, Principle, to verify the shortcomings already communicated by this department vide letter No. F6/DFS/MS/School/2011/2697 dated 24.10.2011

During the inspection, it was observed that the school building is comprises of ground plus three upper floors. Fire fighting system such as hydrant, hose reel, extinguishers were found provided and following shortcomings were observed.

1. Fire fighting systems has not commissioned.
2. Hose reels are not fitted with nozzles.
3. 3000 Liters overhead water storage tank found provided against the requirement of 10000 Liters.

In view of above, the fire safety certificate cannot be issued. You are requested to rectify the above said shortcoming under intimation to this department for further course of action.

Yours faithfully

(Rajesh Panwar)

Dy. Chief Fire Officer

Copy to:-

The Dy. Director of Education (Central) Zone No. 27,
Jhandewalan, Near Kali Mandir, New Delhi

ole h