G18



GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI- 110001



No. F6/DFS/MS/EH/WZ/2022/ 672

Dated: 22/11/2022

To

The Joint Commissioner of Police (Lic.), 1st Floor, Police Station Defence Colony, New Delhi.

Sub.:- Regarding issuance of Fire Safety Certificate in r/o M/s. Haldiram Product Pvt. Ltd. located at building No. 06, Vaishali Enclave, Pitampura, New Delhi- 110034.

Sir,

Please refer to the online application No. 202210279441 received through MHA portal, on the subject cited above. In this connection, it is to inform you that the aforesaid restaurant has been inspected by the officer concerned of this department, in presence of Sh. Sudhir Sharma (manager) on 10.11.2022 to check the status of the status of the shortcomings already pointed out by this department vide letter No. F.6/DFS/MS/WZ/2020/50 dated 09.01.2020 and status of the shortcomings is as follow: -

S	Shortcomings	Status
No.		
1	The widths of staircases are less than required width 2.0 & 1.5 mts clear width.	Not Complied
2	Two exit doors 2 m & 1.5 m width are required to be provided both GF & FF.	Provided
3	Hose Reel Hose of 30 m length and hydrant found nonfunctional.	Found Functional
4	Manual Operated Fire Alarm System found nonfunctional.	Found Functional
5	Terrace Fire Pump of 2x450 lpm with 40 m head found nonfunctional.	Required one pump cap. 450 LPM & Provided
6	Terrace tank of 25000 lts capacity is required to be provided.	Required 20,000 lts & Provided

In view of the above shortcoming at sr. No. 01, the application for issuance of Fire Safety Certificate is rejected. The occupancy of the building / premises in absence of requisite Fire safety arrangements shall be at the risk and liability of the owner/occupier.

Copy to: -

- 1. The Deputy Health Officer, North Delhi Municipal Corporation, Keshavpuram Zone, New Delhi.
- 2. Sh. Satish Kaushik, M/s. Haldiram Product Pvt. Ltd., building No. 06, Vaishali Enclave. Pitampura, New Delhi- 110034.