

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI- 110001



No. F6/DFS/MS/WZ/2022/ 2986

Dated: 28 11 2022

To

Sh. Sunil K Jain, Vice President, G-3, Aggarwal Corporate Tower, Plot No.- 23, District Centre, Rajendra Place, New Delhi- 110088.

Sub.:- Regarding renewal of Fire Safety Certificate in r/o M/s. Aggarwal Tower located at building No. H-6, Netaji Subhash Place, Pitampura, New Delhi- 110034.

Sir,

Please refer to your e-mail dated 09.11.2022 received through e-mail id sunilk.jain@unitygroup.in on the subject cited above. In this connection, it is to inform you that the aforesaid building has been inspected by the officers concerned of this department in your presence on 14.11.2022 to check the status of the status of the shortcomings already pointed out by this department vide letter No. F.6/DFS/MS/2019/WZ/2010 dated 05.08.2022 and status of the shortcomings is as follow: -

S No.	Shortcomings	Status
1	Automatic fire detection and alarming system provided but not	Not Rectified
	functional.	
2	Main pump 2850 LPM, standby pump 2850 LPM & Jockey pump 2x225 LPM provided but not on auto mode.	Still not in auto mode & there is heavy leakage in pipeline near pump
3	Exit signages found removed.	Not provided

In addition of above, following shortcomings were also observed: -

1. Sprinklers are covered under false ceiling due to renovation work.

In view of the above shortcoming, the application for renewal of Fire Safety Certificate is rejected. The occupancy of the building / premises in absence of requisite Fire safety arrangements shall be at the risk and liability of the owner/occupier.

Copy to: -