

C-16

**GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUARTERS: DELHI FIRE SERVICE: CANNAUGHT PLACE
NEW DELHI- 110 001**

No. F6/DFS/MS/School/2021/SZ/ 691

Dated: 29/12/2021

To,

The Principal,
M/s Aaryan International School, Plot
No. 320-321, Om Vihar, Phase-I, Uttam Nagar,
New Delhi-110059.

Sub:- Regarding Issuance of Fire Safety Certificate in r/o M/s Aaryan International School, Plot
No. 320-321, Om Vihar, Phase-I, Uttam Nagar, New Delhi-110059.

Sir,

This is in reference to your letter No. AIS/Misc/2021/06 dated 07/12/2021 on the subject cited above. In this connection, it is to inform you that the inspection of above said building has been carried out by officers concerned of this department on 15/12/2021 in presence of Mr. Imran (Principal). During the course of inspection it was observed that the building is comprised of basement, ground floor plus three upper floors but school running at ground floor plus three upper floors. The following shortcomings were observed:-

1. First aid hose reel system provided but not functional.
2. Fire pump having 450 lpm found removed.
3. Exit signage's were found removed.

Keeping in view of above, the building cannot be considered for issuance of fire safety certificate, at this stage. Therefore you are advised to rectify the above said shortcomings under the intimation to this department for further course of action.

Yours Faithfully



(Sunil Chawdhary)
Dy. Chief Fire Officer
Delhi Fire Service



Copy:-

The Director of Education,
Govt. of NCT of Delhi, Old Secretariat, New Delhi-110054.
(With a request to take further action as school does not have fire NOC)