GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI <u>HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI-110001</u>

NO. F-6/DFS/MS/School/2021/682

Dated 27/12/2021

To,

The Principal Shanti Vidya Mandir, D-1, Rajeev Nagar, Bhalaswa Dairy Colony, Delhi-42.

Sub: - Regarding issuance of fire safety certificate in r/o Shanti Vidya Mandir, D-1, Rajeev Nagar, Bhalaswa Dairy Colony, Delhi-110042.

Sir,

Please refer to your letter received through email I.D dated 25.11.2021 on the subject cited above. In this connection this is to inform you that the above mentioned site was visited by the officer concerned of this department on 07.12.2021 to verify the fire safety measures issued vide Director of Education and observed that the school premise is comprised of 02 blocks, ground and ground + one upper floor only. At the time of inspection Sh. Bijender Singh (Attendant) was also present at site. During the course of inspection observations/ shortcomings made are as under:-

- 1. Fire extinguisher provided but not functional at the time of inspection.
- 2. Hose reel hose provided but damaged/leakage condition.
- 3. Terrace level firefighting pump capacity of 450lpm provided but found auto mode system not functional at the time of inspection.
- 4. Terrace level fire water tank capacity of 10,000ltrs is being used for domestic purposes. Fire water tank must be dedicated to firefighting purposes only and there was water till the bottom of the tank.
- 5. Exit signage and floor signage found removed at strategic locations in the building and sand bucket found empty/ damaged condition.

Keeping in view of above, fire safety certificate cannot be considered at this stage

(Dharampa) Bhardwaj

Dy. Chief Fire Officer

Ph:-011-25156707

Copy to:-

1. The Director, Education, Government of N.C.T of Delhi. Old Sectt. Delhi -110054.