



**GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI** c26  
**HEAD QUARTERS : DELHI FIRE SERVICE : NEW DELHI – 110001**

No.F6/DFS/MS/School/2021/10

Dated: 12/01/2022

To

The Principal,  
EDMC Primary School,  
S-Block, Pandav Nagar, Delhi.

**Sub: Regarding issuance of FSC in r/o EDMC Primary School located at S-Block, Pandav Nagar, Delhi.**

Sir,

This has reference to letter no. E.E(Elect.)-II/Shah(S)/2021-2022/D-570 dated 27/10/2021 on the subject cited above. In this regard, it is to inform you that the site was inspected by the officer concerned of this department on 16/12/2021 in the presence of Mrs. Jyotsana (Principal) and observed that no progress was seen on the observations communicated by this department vide letter no. F6/DFS/MS/School/2014/2427 dated 22/10/2014 (photo copy enclosed).

Hence, the Fire Safety Certificate cannot be considered at this stage. You are requested to rectify the shortcomings under the intimation to this department for further necessary action in this regard.

Yours faithfully



**(Dr. S.K. Tomar)**  
Dy. Chief Fire Officer  
Delhi Fire Service



Encl:- as above.

Copy to:-

The Director (Education),  
EDMC, 419, Udyog Sadan,  
Patparganj Industrial Area, Delhi - 92.

C 18

**GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI**  
**HEADQUARTERS: DELHI FIRE SERVICE: CANNAUGHT PLACE**  
**NEW DELHI- 110001**

No. F6/DFS/MS/School/2014/2427

Dated: 22/10/14

To,

The Principal (1<sup>st</sup> Shift)  
EDMC Primary School,  
S-Block, Pandav Nagar, Delhi-92

**Sub:** - Regarding issue of "Fire Safety Certificate" from fire safety point of view in r/o EDMC Primary School, S-Block, Pandav Nagar, Delhi

Madam,

Please refer to your letter dated nil received from EDMC Education department on the subject cited above. In this connection this is to inform you that officer concerned of this department inspected the school to verify the fire safety arrangements in accordance with the circular No. F.16/Estate/CC/Fire Safety/2011/3298 to 3398 dated 01.03.11 issued by the Director of Education. At the time of inspection In-charge was present and it was observed that the school building is comprised of ground plus two upper floors and have following shortcomings:-

1. An additional staircase having width not less than 0.75 m is required.
2. First Aid Hose reels not provided.
3. Fire pump having 450 LPM out put at 40 m head not provided.
4. Over head water storage tank 10,000 liters capacity for firefighting not provided.
5. Exit signs not provided.

In view of above, the fire safety certificate cannot be considered at this stage. You are requested to rectify the above shortcoming under the intimation to this department for further course of action.

Yours faithfully

  
(Dr. G.C. Misra)

Chief Fire Officer

Ph -011- 23414333

Copy to:-

- 1 The Director of Education,  
East Delhi Municipal Corporation,  
419, Udyog Sadan, Patparganj Industrial Area, Delhi-92
2. The Principal (2<sup>nd</sup> Shift)  
EDMC Primary School, S-Block, Pandav Nagar, Delhi