

5  
e 11

**GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI**  
**HEADQUARTERS: DELHI FIRE SERVICE, CONNAUGHT PLACE**  
**NEW DELHI- 110001**

No. F6/DFS/MS/School/2022/SZ/ 13

Dated: 14/01/2022

To,


The Manager,  
D.D. Gyan Jyoti Public School,  
RZ-R-51-52, Chanakya Place Part-II,  
New Delhi-110059.

**Sub:-**Regarding issue of "Fire Safety Certificate" from fire safety point of view in r/o D.D. Gyan Jyoti Public School, RZ-R-51-52, Chanakya Place Part-II, New Delhi-110059.

Sir,

This has reference to your letter no. Nil dated 29/12/2021 on the subject captioned above. In this connection, it is to inform you that the above mentioned building/premises was inspected by the officer concerned of this department on 07/01/2022 in the presence of Manager to verify the compliance of shortcoming already communicated by this department vide letter no. F6/DFS/MS/School/2020/SZ/122 dated 19/02/2020 and observed that shortcomings are still not rectified. The management will be held responsible for any untoward incident for the period if compliance is not made.

Yours faithfully



(Sunil Chawdhary)  
Dy.Chief Fire Officer

etc.

Copy to:-

1. The Director of Education,  
Govt. of NCT of Delhi, Old Secretariat,  
New Delhi-110054.

**(With a request to take further action as school does not have fire NOC)**

c.7

**GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI  
HEADQUARTERS: DELHI FIRE SERVICE, NEW DELHI-110001**

No: F.6/DFS/MS/School/2020/SZ/122

Dated: 19/02/2020

To,

The Manager,  
D.D. Gyan Jyoti Public School,  
RZ-R-51-52, Chanakya Place Part-II,  
New Delhi-110059

Sub: - Regarding issuance/renewal of Fire Safety Certificate in r/o D.D. Gyan Jyoti Public School, RZ-R-51-52, Chanakya Place Part-II,, New Delhi-110059.

Sir/Madam,

This has reference to your Letter No. Nil dated 16.12.19 on the subject cited above. In this connection, it is to inform you that the inspection of above said school building has been carried out by officer concerned of this department on 20.01.2020 to see the compliance of the requisite fire safety measures. Sh. Rajinder Gambhir was present at the time of inspection.

During the course of inspection it was observed that school building comprised of ground floor only of a building comprised of ground floor plus one upper floor & one room on terrace was issued FSC by this department vide letter no. F.6/DFS/MS/School/2016/SZ/1841 dated 26.12.2016. But now additional room have been constructed on terrace (i.e. second floor). As this is a case of addition/alteration you are advised to submit the completion/sanctioned plans through building department (i.e. SDMC/DDA) for construction of new room on terrace (i.e. second floor).

Yours Faithfully,

(ATUL GARG)  
DIRECTOR  
DELHI FIRE SERVICE

Copy to:-

1. The Executive Engineer (Bldg.),  
HQ-II, SDMC, 8<sup>th</sup> Floor, Dr. S.P.M Civic Centre,  
E-Wing, J.L. Nehru Marg, New Delhi-110002 (for taking necessary action)
2. Director of Education,  
Govt. of NCT of Delhi, Old Secretariat,  
New Delhi – 110054  
(with a request to take further action as school does not have fire NOC)

ACSD  
19/2/2020