

C-25

**GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI  
HEADQUARTERS: DELHI FIRE SERVICE, NEW DELHI-110001**

No: F.6/DFS/MS/School/2022/SZ/ 79

Dated: 23/02/2022

To,

The Principal,  
Saraswati Model School,  
Street No.-5, East Sagarpur, New Delhi-46.

Sub: - Regarding issuance of Fire Safety Certificate in r/o. Saraswati Model School, Street No.-5,  
East Sagarpur, New Delhi-46.

Sir,

This has reference to your Letter No. Nil dated 04/02/2022 on the subject cited above. In this connection this is to inform you that officer concerned of this department inspected the school on 09/02/2022 to verify the fire safety arrangements in accordance with the rules. At the time of inspection Sh. Sunil Jain (Principal) was present and it was observed that the school building is comprised of ground plus three upper floors and have following shortcomings.

1. Both staircases should be widened 1.5 meter each.
2. Hose reels are provided but not functional.
3. Fire pump having 220 lpm provided in place of 450 lpm at terrace.
4. Over head water tank 5000 liters in place of 10,000 liters.
5. Exits signage's are not provided

In view of above, the fire safety certificate cannot be considered at this stage. You are requested to rectify the above shortcoming under the intimation to this department for further course of action.

Yours faithfully



(Ajul Garg)

**Director**

Delhi Fire Service



Copy to:-

1. The Director of Education, Govt of NCT of Delhi, Old Secretariat, New Delhi-110054.(with a request to take further action as school does not have fire NOC)