

C-14

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUARTERS: DELHI FIRE SERVICE, NEW DELHI-110001

No. F6/DFS/MS/GH/2022/ 192

Dated: 04/03/2022

To,

Authorized Signatory,
Shanit Guest House, 46,
Ram Vihar, Delhi-110092.

Subject: Inspection report of M/s Shanit Guest House, 46, Ram Vihar, Delhi-110092 from Fire Safety and means of escape point of view.

Sir,


Please refer to your letter received through MHA portal application No. 2021122429276 dated 14/02/2022 on the subject noted above, in this connection, it is to inform you that the said premises was inspected by the officers concerned of this department on 18.02.2022 in the presence of Mr. Mukesh Sharma.

During the course of inspection it was observed that the building premises is comprised of Basement, Ground Floor & Three Upper Floors only and observations are as per under:-

1. Width of corridor 1.64 mtr provided against requirement of 1.80mtr (Double Loaded).
2. Hose reel hose provided but nonfunctional.
3. Internal hydrant provided but nonfunctional
4. Fire pump of 450 LPM & 900 LPM Provided but non functional.
5. Exit signage not provided.

In view of above shortcomings, the application for issuance Fire Safety Certificate is rejected. The occupancy of the building / premises in absence of requisite fire safety arrangements shall be at the risk and liability of the owner / occupier. The Licensing Authority / Statutory Authority may take suitable necessary action as deemed fit.

Yours faithfully,


(ATUL GARG)
DIRECTOR.
o/c

Copy to:-

1. Joint Commissioner of Police (Lic), 1st Floor, Police Station Defence Colony, New Delhi-110049.