

**GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEAD QUARTERS, DELHI FIRE SERVICE, NEW DELHI -110001**

No.F6/DFS/MS/School/NDZ/2022/93

Dated:- 04/02/2022

To

The Principal,
The Neev School,
B-7, Gurudwara Road, I.P Extension,
Patparganj, Delhi-92.

Sub: Regarding renewal of FSC in r/o The Neev School located at B-7, Gurudwara Road, I.P Extension, Patparganj, Delhi-92.

Sir,

This has reference to your email dated 09/02/2022 on the subject cited above. In this regard, it is to inform you that the site was re-inspected by the officer concerned of this department on 25/02/2022 in the presence of Mrs. Anshu Goel (Principal) and observed that the shortcomings already communicated by this department vide letter No. F6/DFS/MS/2019/7683 dated 20/12/2019 (photocopy enclosed) has not been rectified yet.

Further for approval of scheme of fire fighting system and addition of staircase as discussed you are requested to route your application through building department of EDMC online portal.

Yours faithfully

(Atul Garg)
Director

Delhi Fire Service

Encl: as above

0/2
MD

C-9

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUARTERS: DELHI FIRE SERVICE: CANNAUGHT PLACE
NEW DELHI- 110001

No. FS/DFS/MS/School/2019/ 7683

Dated: 20/12/19

To,

The Principal,
The Neev School B-7, Gurudwara Road,
I.P.Extension, Patpargang, Delhi-92.

Sub: - Regarding issue of "Fire Safety Certificate" from fire safety point of view in r/o
The Neev School B-7, Gurudwara Road, I.P.Extension, Patpargang, Delhi-92.

Sir,

Please refer to your letter no. dated 02/12/19 on the subject cited above. In this connection this is to inform you that officer concerned of this department inspected the school to verify the fire safety arrangements in accordance with the NBC Part-IV. At the time of inspection Mrs. Anshu Goel (Principal) was present and it was observed that the school building is comprised of ground plus three upper floors and have following shortcomings.

1. The width of staircase is less than 1.5 m for both the staircases & should lead to terrace.
2. First Aid Hose reels not provided.
3. Over head water storage tank 10,000 liters capacity not provided.
4. Fire pump having 450 LPM out put at 40 m head not provided.
5. Exits signage's are not provided.

In view of above, the fire safety certificate cannot be considered at this stage. You are requested to rectify the above shortcoming under the intimation to this department for further course of action.

Yours faithfully



(Sunil Chawdhary)
Dy.Chief Fire Officer

Copy to:-

- The Director of Education,
Udyog Sadan, Plot No. 419, FIE,
Patpargang Industrial Area, Delhi-110092.