

C32

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUARTERS : DELHI FIRE SERVICE : NEW DELHI – 110001

No. F.6/DFS/MS/School/NDZ/2022/ 125

Dated: 21 / 03 / 2022

To

The Principal,
Jai Bharat School,
Chawri Bazar, Delhi-110006.

**Sub: Regarding issuance of Fire Safety Certificate (FSC) in r/o Jai Bharat School,
Chawri Bazar, Delhi -110006.**

Sir,

This is in reference to letter no. nil dated 07.03.2022 on the subject cited above. In this connection, it is to inform you that the above mentioned premise was visited by the officer concerned of this department on dated 15.03.2022 and observed that the shortcomings intimated vide letter no. F.6/DFS/MS/SCHOOL./2014/368 dated 13.02.2014 have not been complied yet. (Copy enclosed for ready reference).

In view of above shortcomings, the application for issuance Fire Safety Certificate is rejected. The occupancy of the building/premises in absence of requisite fire safety arrangements shall be at the risk and liability of the owner/occupier. The Licensing authority/ Statutory Authority may take suitable necessary action as deemed fit.

Yours faithfully,



(Dr. S. K Tomar)
Dy. Chief Fire Officer
Tel:011-23412025

Copy to:-

The Directorate of Education, North Delhi Municipal Corporation, Dr. SPM Civic Center, JLN Marg, New Delhi.

8
21/03

923

**GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUARTERS: DELHI FIRE SERVICE: CANNAUGHT PLACE
NEW DELHI- 110001**

Ph - 23412025 Email - dcfondz.dfire@nic.in

No. F6/DPS/ms/school/2014/368

Dated: 13/02/14

To,

The Principal,
Jai Bharat School,
Chawri Bazar, Delhi-110006.

Sub: - Regarding issue of "Fire Safety Certificate" from fire safety point of view in r/o Jai Bharat School, Chawri Bazar, Delhi-110006.

Madam,

Please refer to your letter No. Nil dated 06.01.2014 on the subject cited above. In this connection this is to inform you that officer concerned of this department inspected the school on 6.2.2014 to verify the fire safety arrangements in accordance with the circular No. F.16/Estate/CC/Fire Safety/2011/3298 to 3398 dated 01.03.11 issued by the Director of Education. At the time of inspection Mrs. Leena Sharma (Principal) was present.

It was observed that the school building comprises of ground plus two upper floors and school is running on first and second floors. Ground floor is commercial. Fire fighting systems such as fire extinguishers and fire buckets were found provided and following shortcoming was observed.

1. An additional staircase not less than 75 cm width is required as the width of the existing single staircase is less than 1.5 meters.
2. A hose reel of 30 meters length fitted with 5mm shut-off nozzle on each floor connected with a pump of 450 LPM capacity (40 meters head) on terrace with 10000 liters overhead tank exclusively for firefighting not provided.
3. Exit signs not provided at all exits and escape routes at appropriate locations.

In view of above, the fire safety certificate cannot be issued at this stage.

Yours faithfully


(Rajesh Panwar)

Dy.Chief Fire Officer

Copy to:-

The Director of Education, NorthDelhi Municipal Corporation,
Dr. SPM Civic Centre, JLN Marg, N.D

