## GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: CANNAUGHT PLACE **NEW DELHI- 110 001**

No.F6/DFS/MS/School/2022/NDZI 135

Dated: 24/03/2022

To.

The Principal Dr. Zakir Husain Memorial Sr. Sec. School Jafrabad, Delhi-110053.

Subject: -Regarding grant of Fire Safety Certificate in r/o Dr. Zakir Husain Memorial Sr. Sec. School located at Jafrabad, Delhi-110053.

Sir.

With reference to your email pku738@gmail.com dated 11/02/2022 on the subject cited above. In this regard, it is to inform you that, the inspection of the above said premises was carried out by the officer concerned of this department in presence of Mr. M. M. Khan, HOS of the school on dated 07/03/2022. During the inspection it was earlier vide that the shortcomings as communicated observed F6/DFS/MS/School/2021/NDZ/514 dated 24/09/2021 have not been complied as yet (The copy of the same is enclosed for reference).

In view of the above Fire Safety Certificate cannot be considered at this stage. You are once again requested to rectify the said shortcoming under intimation to this office for further consideration in the matter.

Yours faithfully

(Dr. S. K. Tomar) Dy. Chief Fire Officer

Copy to:-

The Director of Education, B-Block, Yamuna Vihar, Delhi-110053

## GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI- 110001

No. F.6/DFS/MS/School/2021/NDZ/ 5/4

Dated: 24 09 2021

To,

The Principal,
Dr. Zakir Husain Memorial Senior Secondary School,
Jafrabad, Delhi-110053

Subject:- Request for renewal of N. O. C. regarding fire safety measures in the school.

Sir,

With reference to your letter No. DZHS/D/DFS/NOC/21/217 dated 13/08/2021 on the subject cited above, it is informed that officer concerned of this department inspected the school from fire safety point of view in presence of Dr. M. M. Khan on dated 06/09/2021. The school building comprises of ground plus three upper floors. During the course of inspection following observations were made:-

- 1. The fire pump was not functional.
- 2. Hose Reel was not functional and also hose reels are required to be provided at ground & IIIrd floor.

In view of the above, the school building cannot be considered for issuance of Fire Safety Certificate at this stage. Therefore, you are requested to provide the above mentioned fire safety arrangements under intimation to this office for further course of action.

Yours Faithfully,

(Dr. S. K. Tomar) Dy. Chief Fire Officer

Copy to:-

The Joint Director of Education, (Land & Estate), Directorate of Education, Lucknow Road, Delhi-110054