



GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI- 110001

752
आशाहीन
अपूर्व महोदय

No. F6/DFS/MS/2022/School/ 752

Dated 21/12/2022

To,

The Principal
Queen Mary's School Northend
Plot no. 4-A, Model Town- III,
Delhi-110009.

Sub: - Regarding issuance of fire safety certificate in r/o Queen Mary's School Northend located at Plot No. 4-A, Model Town-III, Delhi-110009.

Sir,

Please refer to your letter no. QMS/Fire Deptt/2022/324 dated 21.11.2022 on the subject cited above. In this connection this is to inform you that the above mentioned site was visited by the officer concerned of this department on 06.12.2022 at the time of inspection Mr. Sandeep Masih (Admin Officer) was also present at site. During the course of the inspection it is observed that the building is comprised of Ground & 04 upper floors with separate basement only. Your request for FSC is rejected under Rule 37 (3) due to following shortcomings.

- 1 The width of 06m internal road and 09m on turning radii at one side is obstructed by concrete wall.
- 2 Fire check doors found removed from all staircase and lift entries.
- 3 The door provided in the activity class room at 4th floor is less than 02m wide.
- 4 Terrace level firefighting pump are not an auto mode.
- 5 There is one lifts provided in the building without lift lobby and lift shaft and lobby's are not pressurized.
- 6 03 nos. of staircases provided from ground to terrace level against the requirements of 04 nos. as per guide lines.
- 7 Basement second staircase blocked by iron almirahs needs to be removed.
- 8 Exits, floors & lift signage's, found removed at some places.

Keeping in view of above, fire safety certificate cannot be considered at this stage

Yours faithfully


(Atul Garg)
Director

Ph: 011-23414000

of e p

Copy to:-

1. The Director of Education, Government of N.C.T of Delhi, Old Seett, Delhi - 110054.