

**GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUARTERS: DELHI FIRE SERVICE, NEW DELHI-110001**

No: F.6/DFS/MS/School/2023/WZ/ 13

Dated: 09/01/2023

To,

Er. Shashank Sahu,
Assistant Engineer (E), PWD, Sub-Division-2,
Edu. Elect. Edn. 1, Div. (N)
Sector-16, Rohini, Delhi-110089.

Sub: - Regarding issuance of Fire Safety Certificate in r/o Sarvodaya Vidyalaya (ID-1413181), New Building, located at Jaunti, Delhi-110081.


Sir,

This has reference to your letter no. 54(9)AE(E)-2/Edu.Elect.Edn.1 Div.(N)/2022-23/60 received via email id dated 20.12.2022 on the subject cited above. In this connection, it is to inform you that the inspection of above said school building has been carried out by officer concerned of this department on 03.01.2023 to see the compliance of the requisite fire safety measures. Sh. Sanjay Chauhan was present at the time of inspection. During the course of inspection it was observed that school building was comprised of Ground floor plus three upper floors. Your request of issuance of FSC is rejected as the following shortcomings were observed:-

1. Fire extinguishers not provided.
2. First-Aid Hose Reels provided but not functional.
3. Terrace level fire pump of 450 lpm capacity not provided.

You are advised to rectify the above-mentioned shortcomings for taking further action as necessary for issuance of Fire Safety Certificate.

Yours Faithfully


(Atul Garg)
Director
Delhi Fire Service